FLEET TEAM DIGEST

737MAX-FTD-25-18004

Issue Title : BE Lavatory Mechanical Faucet Improvements

Airplane Model	ATA	Minor Model(s)
737MAX	2540-00	-7, -8, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
10/10/2018	02/19/2019	01/28/2019

Estimated Completion Date	Next Update Date

Revision Description

Updated FTD to incorporate Supplier Service Bulletin information.

Applicability

All 737NG and 737 MAX airplanes installed with Rockwell Collins/BE Aerospace mechanical faucets P/N AR9472-3W1D492 and PN SC4L500301-1.

Description

Operators have reported the mechanical lavatory faucets leaking. The water continues to drip when the faucet is turned off. Boeing and the faucet manufacturer, BE Aerospace/Rockwell Collins, have investigated the cause of the leaking faucets. The cause is due to contamination that adheres to the spigot causing the spigot to stick open which causes leakage. BE released Supplier Service Bulletin and Service Letter 4w2-38-0001 and 4w2-38-0002 respectively to address faucet splash back, and leaking issues.

Background

Status

BE Aerospace has redesigned the faucet to prevent contamination and to correct the splashback issue by revising the aerator to improve fluid flow. The new faucet PN SC4L500301-4 has been certified and will be incorporated on Airplane LN 7150.

Interim Action

BE Aerospace is providing a Supplier Service Bulletin to enable retrofitting previous generation 1.0 Faucets PN SCL500301-1 to be upgraded to the new 1.2 Faucets PN SC4L500301-4 at no cost.

Final Action

Rockwell Collins/BE Aerospace made improvements to the mechanical faucets. The Supplier has released Supplier Service Letters: 4W2-38-0001 and 4W2-38-0002 to revise the faucet aerator to provide instructions on replacing the faucet cartridge for

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

the leak issue.
BE Aerospace/Rockwell Collins has released Rockwell SB 1L3-25-0064 (Rev -), which provides retrofit of 1.0 generation faucets to the new 1.2 generation faucets.

Boeing has incorporated the modified lavatory faucets in production on 737 airplane line position # 7150.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Production Incorporation: 737 Line # 7150 (complete)

Supplier Service Bulletin (SC4L500301-1) Available: 14-MAY-2018 (complete)

Supplier Service Letter (SC4L500301-4) Released: 09-AUG-2018 (complete)

Parts Available: 09-AUG-2018 (complete)

Supplier Service Bulletin (1L3-25-0064) Released: DEC-2018 (complete)

Operator Action

Review and Incorporation as required of the BE Aerospace Service Bulletin and Service Letter to improve the performance and reliability of the mechanical faucets.

Part Information

BE Aerospace/Rockwell Collins Mechanical Faucet P/N SC4L500301-1 and SC4L500301-4

Supplier Information

Rockwell Collins/BE Aerospace

Lavatories

Interior Systems

11404 Commando Rd, Everett, WA 98204

rockwellcollins.com

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	1L3-25-0064	Rev -	10/18/2018
Service Bulletin (SB)	4W2-38-0001		05/14/2018
Service Letter (SL)	BE Aerospace SL-4W2-38-0002		08/09/2018

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Lavatory Faucet			SC4L500301-1
Lavatory Faucet			SC4L500301-4
Lavatory Faucet			AR9472-3W1D492

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991