FLEET TEAM DIGEST

737MAX-FTD-25-19001

Issue Title : Safran Cabin Coffee Maker

Airplane Model	ATA	Minor Model(s)
737MAX	2531-00	-7, -8, -8200, -9

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
03/13/2019	07/28/2020	07/23/2020

Estimated Completion Date	Next Update Date

Revision Description

Updated Status paragraph for "Fuse Holder". Updated Final Action date for improvement of fuse holder PCBs. Updated Milestone target dates of design improvement for Defective Fuse Printed Circuit Boards to "complete". This action closes this FTD article.

Applicability

737 MAX with P/N 900X-XX-0000-XX and P/N 920X-XX-0000-XX Coffee Maker installed

Description

Safran has identified product improvement opportunities for their coffee makers to enhance 737 in-service performance and further increase reliability.

Background

737 MAX operators have been experiencing Safran Coffee Maker component removals early into service.

There has been an increase in P/N 900X-XX-0000-XX and P/N 920X-XX-0000-XX Coffee Maker component removals across the 737MAX fleet.

The failure modes identified are as follows:

- Defective Temperature Sensor

- Leaking Coffee Maker

- Defective Printed Circuit Board (PCB)

- Mechanical Defect

Status

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

1. Temperature Sensor

An investigation into the temperature sensor failure yielded the discovery of the temperature sensor P/N TT4-100KC6-22-BE4 as defective. A micro crack in the stainless steel material was found to be caused by drilling at the supplier. This issue has been addressed by product improvement of the temperature sensor P/N TT4-100KC6-22-BE4 since November 2018 per SIL351.

2. Overheated Contacts

An investigation concluded that the gold plating at the crimping area in the current installation is not thick enough to withstand redox reaction. The crimp barrel has been identified as being too big and the material thickness requires updating. This issue was addressed by a product improvement. Implementation began in March 2019 via SB9002-25-01.

3. Fuse Holder

There have been a series of overheated printed circuit boards (PCBs) in the area of the fuse carrier causing the product to stop functioning. The root cause is an irregular coating with tin which reduces the hardness and spring force for the fuse carrier. Beginning in September 2018, Safran has been inspecting all fuse carriers and PCBs in stock and on the shop floor and fuse carriers have been replaced. Affected PCBs have been identified and are being changed during workshop visits in accordance with the CMM. Safran submitted a supplier NOC to Boeing and has incorporated Boeing's comments. The NOC was approved by Boeing on 25-FEB-2020. The design improvement for the fuse holder PCBs was incorporated by 31-MAR-2020. No SIL or SB is needed for this change because any failed in-service units will be replaced on attrition via the CMM.

4. Water Boiler Drain Plug

Traces of rust and potential rust contamination has been found in the coffee makers. Safran has investigated and attributes the root cause to be that the raw material of the screw installed in the water tank was delivered with the incorrect raw material. SIL353 was issued to operators to inform of a cleaning procedure for tanks and water system from concert coffee/beverage maker and concert water boiler, as well as to have operators ensure the correct stainless steel screw P/N GN749-G1/8-B is installed.

Interim Action

None

Final Action

Concert Coffee/ Beverage Maker Technical Improvements:

-Drain Plug Screw in September 2018 - SIL353

-Improved Temperature Sensors implementation in November 2018 – SIL351

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

-Prevention for Overheating contacts in March 2019 – SB 9002-25-01

-Improvement of fuse holder PCBs – 31-MAR-2020 (completed), no SIL/SB necessary

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Temperature Sensor

Root Cause Established: 15-JAN-2018 (completed)

Solution Selected: 31-MAR-2018 (completed)

Change Committed: 31-MAY-2018 (completed)

Production Incorporation: 30-NOV-2018 (completed)

Service Bulletin Available: 30-NOV-2018 (completed)

Parts Available: 30-NOV-2018 (completed)

Water Boiler Drain Plug

Root Cause Established: 15-JAN-2018 (completed)

Solution Selected: 15-MAR-2018 (completed)

Change Committed: 15-MAY-2018 (completed)

Production Incorporation: 30-SEP-2018 (completed)

Service Bulletin Available: 30-SEP-2018 (completed)

Parts Available: 30-SEP-2018 (completed)

Defective Fuse Printed Circuit Boards (PCBs)

Root Cause Established: 15-SEP-2018 (completed)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Solution Selected: 15-MAY-2019 (completed)

Change Committed: 30-SEP-2019 (completed)

Production Incorporation: 31-MAR-2020 (completed)

Service Bulletin Available: N/A

Parts Available: 31-MAR-2020 (completed)

Overheated Contacts

Root Cause Established: 15-FEB-2018 (completed)

Solution Selected: 15-JUL-2018 (completed)

Change Committed: 15-NOV-2018 (completed)

Production Incorporation: 31-MAR-2019 (completed)

Service Bulletin Available: 31-MAR-2019 (completed)

Parts Available: 31-MAR-2019 (completed)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Information Letter (SIL)	SIL351		11/30/2018
Service Bulletin (SB)	SB-9002-25-01		01/31/2019
Service Information Letter (SIL)	SIL353		09/28/2018

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- Significant Event Report : List of significant in-service or maintenance events reported to Boeing that result in
  Air turnbacks, ground turnbacks, diversions, rejected takeoffs, in-flight shutdowns, or Significant AOGs.
  High failure rate of costly/critical systems

Attachments:

a) Drain Plug Location

b) PCB containing Defective Fuse Carriers

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

c) Overheated Connector

d) Temperature Sensor

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991