FLEET TEAM DIGEST

737MAX-FTD-25-21001

Issue Title : 737 MAX Inadvertent In-Cabin Slide Inflation

Airplane Model	ATA	Minor Model(s)
737MAX	2566-00	-8, -9, -BBJ

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
02/19/2021	06/20/2023	12/01/2022

Estimated Completion Date	Next Update Date

Revision Description

Revised to add NPRM and AD to References and Status sections.

Applicability

737 MAX airplanes equipped with P/N 5A3307-7 escape slides

Description

737NG operators have reported several inadvertent deployments of the emergency door exit escape slides related to the 5A3307 series escape slides where insufficient slack in the inflation cable and movement of the escape slide inside the compartment have caused inflation of the escape slide while still inside the compartment.

On 20 Aug 2020, Service Related Problem (SRP) 737NG-SRP-25-0427 was assigned to further evaluate root cause and potentially develop a directly implementable solution.

On 30 Oct 2020, a decision was made to have a modification of the escape slides via a part number roll. Supplier will proceed with producing and releasing a new part number escape slide within a service bulletin. The service bulletin will include all required document revisions.

Originally, the 737 MAX was not affected as they were delivered with 5A3307-7 Slides Post SB 5A3307-25-451. With this part number roll, the 737 MAX is now affected.

Current supplier SB 5A3307-25-451 containing the design change has been revised to reference a new SB 5A3307-25-517 as applicable and includes both the 737NG and 737 MAX. The new SB 5A3307-25-517 will only re-part mark all 5A3307-7 slides to 5A3307-701 slides indicating SB 5A3307-25-451 has been incorporated.

Status

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

The FAA has released NPRM Docket No. FAA-2022-1410 followed by AD 2023-09-04 that is related to Requirements Bulletin 737-25-1866.

Interim Action

Operators should incorporate Supplier's Service Bulletin SB 5A3307-25-451 that modifies the escape slides to avoid inadvertent inflation.

Final Action

Boeing issued Special Attention Service Bulletin SB 737-25-1866 to require operators to implement supplier's new SB 5A3307-25-517 and existing supplier's SB 5A3307-25-451 (Rev 2) that modifies or replaces escape slides to avoid inadvertent inflation, including compliance time and applicability.

Boeing Special Attention SB directs operators to swap out **ANY** 5A3307-7 for a -9 or -701. It also directs them to the new Supplier SB 5A3307-25-517 for bringing a 5A3307-7 up to a -701.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: Apr-2016 (completed)

Solution Selected: Aug-2016 (completed)

Compliance Recommendation: 05-Apr-2021 (completed)

Lead Airline Call (LAC) Intro: 16-Sep-2020 (completed)

Lead Airline Call (LAC) Status Update: 30-Sep-2020 (completed)

Lead Airline Call (LAC) Status Update: 09-Dec-2020 (completed)

Lead Airline Call (LAC) Status Update: 03-Feb-2021 (completed)

Request For Information (RFI) Submitted to Supplier: 20-Nov-2020 (complete)

Special Attention Service Bulletin 737-25-1866 (737 MAX) Available: 27-Sep-2021 (complete)

Supplier Service Bulletin 5A7707-25-451 Revision Available: 21-Apr-2021 (complete)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Supplier Service Bulletin 5A7707-25-517 Available: 21-Apr-2021 (complete)

Part Information

Evacuation Slide part number 5A3307-7

Supplier Information

COLLINS AEROSPACE (formerly Goodrich Corporation)

3414 South Fifth Street

Phoenix, AZ 85040 USA

Office: +1.602.232.4037

collinsaerospace.com

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Airworthiness Directive (AD)	2023-09-04		05/25/2023
Service Related Problem (SRP)	737NG-SRP-25-0427		08/20/2020
Service Bulletin (SB)	5A3307-25-451	2	04/21/2021
Service Bulletin (SB)	5A3307-25-517	Orig	04/21/2021
Service Bulletin (SB)	SB 737-25-1866	Rev R00	09/27/2021
Notice of Proposed Rule Making (NPRM)	Docket No. FAA-2022-1410; Project Identifier AD-20		01/17/2023

Related Categories

- SRPs - Economic : Service Related Problems in work by Boeing that have an economic impact

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991