FLEET TEAM DIGEST

737MAX-FTD-25-23002

Issue Title : Collins Aerospace 1L3000 series Lavatories with Bifold Doors - Improper Function

Airplane Model	ATA	Minor Model(s)
737MAX	2540-00	-8, -9

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
03/16/2023	07/11/2023	06/01/2023

Estimated Completion Date	Next Update Date
10/29/2023	10/29/2023

Revision Description

Updated Milestone section dates and a clarifying note in the Status section.

Description

Boeing and Collins Aerospace have received reports of Collins Aerospace 1L3000 series Lavatories with Bifold Doors found stuck in the closed position or improperly functioning in service.

Collins Aerospace has determined the root cause to be loose or protuding screws in the top trim of the bifold door preventing proper functioning of door opening/closing.

Status

Collins Aerospace has released Service Letter, SL-1L3-25-0043 Rev 01, that recommends repeat inspections every 3 months or 1000 flight hours to ensure proper operation of the bifold door. Refer to Paragraph 3. Accomplishment Instructions of Service Letter, SL-1L3-25-0043 Rev 01. Boeing notes that Collins Process Specification LCPS-5071 provides allowance for a screw up to two grip lengths (longer or shorter) may be used. This allowance is reflected in SL-1L3-25-0043 Rev 01 as it lists the option to install the longer screws as a result of a failed inspection.

Collins Aerospace intends to implement a design change to replace the discrepent screws with longer screws to ensure proper engagement with the bifold door trims. Upon approval of the design change, Collins Aerospace will release a service bulletin to replace the screws for the in-service fleet.

Interim Action

Boeing advises operators to review the recommened inspections provided in Collins Service Letter, SL-1L3-25-0043 Rev 01.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Final Action

Collins Aerospace will release a service bulletin to replace the descrepent screws with longer screws.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: Complete
Solution Selected: Complete
Change Committed: April-2023 (Complete)
Production Incorporation: October-2023 (Target)
Collins Supplier Service Bulletin Available: October-2023 (Target)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Drawing	Collins Process Specification LCPS-5071		
Service Information Letter (SIL)	Collins SL-1L3-25-0043	01	

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991