FLEET TEAM DIGEST

737MAX-FTD-25-23006

Issue Title : 737 Safran Cabin Galley Electrical Insert Failures

Airplane Model	ATA	Minor Model(s)
737MAX	2531-00	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
10/13/2023	10/13/2023	10/12/2023

Estimated Completion Date	Next Update Date

Applicability

All 737MAX airplanes with P/N 900X Coffee Maker, P/N 920X Beverage Maker, P/N 940X Water Boiler and P/N 830X Oven installed.

Description

Boeing has received reliability reports from 737MAX operators who have been experiencing Safran component removals early into service.

Background

There has been an increase in P/N 900X Coffee Maker, P/N 920X Beverage Maker, P/N 940X Water Boiler and P/N 830X Oven component removals across the 737MAX fleet. The failure modes that have been identified are as follows:

Coffee Maker / Beverage Maker / Water Boiler

- Red fault light illuminated, units will not brew/boil. - Investigation found that temp sensor failed
- Water ingress is root cause of sensor failure. - Thermal cycling caused plastic housings to expand/retract leading to water ingress

Oven

- Failure of oven F22 fault code. F22 failure code indicates an intermittent temp sensor - Investigation found the sockets within the connector were oblong

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

- Damage to the sockets allow for intermittent contact generating the F22 fault code. Sockets damaged when the sensors are disconnected. Disconnecting the sensor using a side to side motion will oblong the sockets

Safran has identified product improvement opportunities for their components to enhance 737 in-service performance and further increase reliability.

Status

Safran has incorporated a design change of P/N 900X Coffee Maker, P/N 920X Beverage Maker, P/N 940X Water Boiler and P/N 830X Oven and released Service Bulletins to address the in-service fleet.

Interim Action

None

Final Action

Coffee Maker / Beverage Maker / Water Boiler

- Safran implemented a design change of temperature sensor, eliminating plastic housing and utilizing a full stainless steel outer shell construction
  - Production cut-in Mar 2023.
- Safran Service Bulletin SB 9002-25-03 (Coffee Maker/Bev. Maker) and SB 9402-25-05 (Water Boiler) released Dec 2022
- Repair stations stocked and equip to perform Service Bulletin
- Sensors will be replaced proactively under warranty

Oven

- Safran implemented Socket material changed to a more robust design, taking into consideration the connection point will be accessed several times throughout the life of the unit
  - Production cut-in Jan 2022
- Service Bulletin SB 8306-25-05 released Jul 2022
- Repair stations stocked and equip to perform Service Bulletin under warranty

Milestones

Not applicable

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Operator Action

Boeing recommends operators to perform the approrpriate Service Bulletin or submit the units to a Safran repair station.

Supplier Information

SB 9002-25-03 / SB 9402-25-05

In case of any failures, malfunctions, defects or other occurrences concerning this modification it should be immediately notified to:

Safran Cabin Germany GmbH.

Phone: +49 (0)2772 707 799 or +49 (0)2772 707 298

E-mail: techsupport.sca@customer.safrangroup.com

Inquiries concerning material and/or prices and/or lead times should be directed to:

Safran Cabin Germany GmbH

Dr. Siegfried Strasse

D-35745 Herborn

Germany

Phone: +49 (0)2772 707 799

Fax: +49 (0)2772 707 551

E-mail: spares.sca@customer.safrangroup.com

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

SB 8306-25-05

In case of any failures, malfunctions, defects or other occurrences concerning this modification it should be immediately notified to:

SELL Design Organization.

Phone: +49 (0)2772 707 529 or +49 (0)2772 707 298

E-mail: ca.inserts.sca@safrangroup.com

Inquiries concerning material and/or prices and/or lead times should be directed to:

Safran Cabin Germany GmbH

Dr. Siegfried Strasse

D-35745 Herborn

Germany

Phone: +49 (0)2772 707 537

Fax: +49 (0)2772 707 546

E-mail: scg.spares@safrangroup.com

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	9002-25-03		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Service Bulletin (SB)	8306-25-05		
Service Bulletin (SB)	9402-25-05		

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- Significant Event Report : List of significant in-service or maintenance events reported to Boeing that result in
  Air turnbacks, ground turnbacks, diversions, rejected takeoffs, in-flight shutdowns, or Significant AOGs.
  High failure rate of costly/critical systems

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991