FLEET TEAM DIGEST

737MAX-FTD-27-18002

Issue Title : Nuisance Latched STALL WARNING SYS L Status Message Causing Operational Delays

Airplane Model	ATA	Minor Model(s)
737MAX	2732-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
09/13/2018	02/24/2026	02/24/2026

Estimated Completion Date	Next Update Date
12/31/2026	09/30/2026

Revision Description

No updates were made to this Fleet Team Digest article.

Applicability

All in-service 737 MAX airplanes.

Description

Boeing receives reports of nuisance latched "STALL WARNING SYS L" status messages shown on the MAX Display System (MDS) Onboard Maintenance Function (OMF) while accomplishing pre-flight procedures. These events typically require maintenance crews to on-board the airplane to troubleshoot and reset the latched status message. These events typically result in operational delays.

Background

The "STALL WARNING SYS L" latched status message is nominally intended to show after the airplane lands and if a fault that affects the left Stall Warning System was detected during the previous flight. A MAINT light will show on the Pilot's overhead panel approximately 30 seconds after touchdown, providing a visual cue to the Pilot that maintenance is required. After the airplane lands, a visual check of the maintenance MAINT light should be performed by the flight crew and reported in the airplane's logbook, to schedule a maintenance activity before the next flight commences.

To the contrary of the nominal functionality described above, a nuisance condition has been identified during on-ground operations and is currently being investigated for root cause and corrective action. This nuisance condition is generically summarized below:

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

1. While the airplane is parked on the ground and is being operated by a maintenance or ground crew, a nuisance "STALL WARNING SYS L" fault can become latched during an airplane power-on or during airplane power sequencing/power transfer activity. The MAINT light and associated OMF "STALL WARNING SYS L" status message is not observed or ignored by maintenance/ground crews during this time.
2. Alternatively, while parked on the ground and while maintenance activities are performed, a nuisance "STALL WARNING SYS L" fault can become latched. The MAINT light and associated OMF "STALL WARNING SYS L" status message is not observed or ignored by maintenance/ground crews during this time.
3. The maintenance and/or ground crews leave the airplane.
4. The flight crew later on-boards the airplane and begins accomplishing the preflight checklist.
5. While accomplishing the preflight checklist, the flight crew observes the MAINT light on and determines that the airplane is in a non-dispatchable condition.
6. A maintenance crew subsequently boards the aircraft and finds a "STALL WARNING SYS L" message shown on the OMF STATUS page.
7. The maintenance crew accomplishes the associated IFIM task for the "STALL WARNING SYS L" observed fault.
8. While accomplishing the IFIM task, no correlated faults nor correlated maintenance messages are found.
9. The maintenance crew performs the Stall Warning System operational test to verify the system is serviceable, then proceeds to manually erase/clear the "STALL WARNING SYS L" status message through the OMF.
10. A operational delay has occurred.

Status

Boeing has identified the root cause of the nuisance latched STALL WARNING SYS L status message. During certain on-ground airplane operations, including power-on, power-transfer activities or during maintenance activities that may involve air mode simulation, the Proximity Sensor Electronics Unit (PSEU) may erroneously transmit "In-Air" discrete information to the Max Display System (MDS) and Stall Management System. The currently fielded MDS software includes independent latching logic for STALL WARNING SYS L and STALL WARNING SYS R status messages. When the MDS processes the "In-Air" discrete input from the PSEU while the airplane is on the ground, the MDS Stall Warning status latching logic can trigger independently of the SMYD, resulting in the nuisance STALL WARNING SYS L status message becoming visible on the OMF maintenance status page and without any correlated faults nor maintenance messages reported by the SMYD.

Boeing is committing changes to the MDS blockpoint software which will remove the latching logic for the STALL WARNING SYS L and STALL WARNING SYS R status messages. This change is anticipated to fully mitigate the nuisance STALL WARNING SYS L latched status message with no correlated fault found scenario that is commonly encountered in-service. With this change, the MDS will no longer be independently capable of latching the stall warning status messages. The SMYD will retain the pre-existing ARINC-429 communication interfaces to the MDS/OMF functions, such that the SMYD will communicate with the MDS to annunciate the STALL WARNING SYS L or STALL WARNING SYS R fault whenever the SMYD detects a legitimate fault has occurred. More specifically, ARINC-429 label 271, bit 15 is set by the SMYD and received by the MDS whenever a fault has been detected which signals the MDS to display the failure annunciation on the OMF page. The majority of faults detected by the SMYD are not latched, meaning that the flight deck failure annunciations will clear automatically once the faults have been removed. The remaining faults detected by the SMYD are latched internally when detected on two consecutive flight legs. When the SMYD latches an internal fault, the flight deck failure annunciations including the OMF status page will continue to show until the fault has been fully corrected and a maintenance technician manually erases the latch directly from the SMYD BITE panel.

As discussed previously, a new SMYD, P/N 285A1010-114 will also be offered to help mitigate some specific in-service problems. Boeing's previous position as conveyed in prior versions of this Fleet Team Digest article was that SMYD P/N 285A1010-114 would address the nuisance condition described above. However, based on Boeing's latest findings and additional commitments to the MDS blockpoint software, the SMYD P/N 285A1010-114 will now include the following functional changes to help reduce other nuisance conditions, none of which were originally latchable by the OMF:

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

- No Computed Data received from the DPC bus (ARINC label 164/Low-Range Radio Altitude) will no longer cause latching of either STALL WARNING SYS L or STALL WARNING SYS R status messages and will no longer result in the SMYD BITE logging fault messages 27-31020 and 27-32020.
- Invalid DPC data received from the DPC bus (ARINC label 164 (LRRA)) will no longer result in the SMYD BITE setting fault messages 27-31021 and 27-32021
- Missing FMC weight/CG data entry will no longer cause the SMYD Existing Fault BITE procedure to generate nuisance maintenance messages 27-31026 and 27-32026.
- Prevent a nuisance STALL WARNING SYS L status message from showing while the airplane is being operated on the ground and the Inertial Reference System (IRS) is not aligned, with correlated faults 34-21991 and 34-22992 found in the OMF.
- Incorporates additional "engine running" discrete information for more robust SMYD air/ground logic.

Interim Action

Until final corrective actions can be fielded, the following interim action is recommended to restore the airplane to a serviceable condition.

- If the MAINT light is illuminated and is accompanied by a STALL WARNING SYS L status message, please perform 737 IFIM Task 27-30-00-810-801 to diagnose and correct the fault.

Final Action

Fielded operators who are affected by this condition are encouraged to incorporate the following service actions when they become available per the milestone date shown below:

- MDS BP2.0 software update in accordance with Boeing Service Bulletin 737-31-1929
- SMYD P/N 285A1010-114 upgrade in accordance with BAE Component Service Bulletin (CSB)

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

SRP Established: 12-Aug-2021 (Complete)

Root Cause Established: 2Q 2022 (Complete)

Solution Selected: 2Q 2022 (Complete)

SMYD P/N 285A1010-114 Component Service Bulletin Available: Post 737MAX-10 type certification.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

MDS BP2.0 Available: please refer to 737MAX-FTD-31-23002 for current information on the schedule release of MDS BP2.0

Operator Action

EMPTY

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Related Problem (SRP)	737MAX-SRP-27-0325		
Multi-Operator Message (MOM)	MOM-MOM-21-0309-01B(R1)		
Fault Isolation Manual (FIM)	IFIM Task 27-30-00-810-801		

Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability
- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message
- Significant Event Report : List of significant in-service or maintenance events reported to Boeing that result in
  Air turnbacks, ground turnbacks, diversions, rejected takeoffs, in-flight shutdowns, or Significant AOGs.
  High failure rate of costly/critical systems

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991