FLEET TEAM DIGEST

737MAX-FTD-27-19001

Issue Title : Spoiler Control Electronics Nuisance Spoiler Control Channel Faults

Airplane Model	ATA	Minor Model(s)
737MAX	2761-00	-8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
12/11/2019	09/04/2026	08/15/2026
Estimated Completion Date	**Next Update Date**	
12/31/2026	11/18/2026	

Revision Description

Revised schedule milestones

Applicability

All 737-8, -8200, and -9 aircraft

Description

Boeing has received several operator reports of Status Message 27-01000 "Spoiler Control Channel" during power up and aircraft turn around. Some operators have also reported that Spoiler Control Electronics (SCE) system test (AMM Task 27-61-45-730-801) could not be executed.

Boeing and BAE Systems have analyzed the non-volatile memory (NVM) downloaded from several returned SCEs. The analysis has identified two root causes that will be addressed in the -0104 Operational Program (OPS) developed for the 737 MAX 10 model and subsequently certified for use on 737-8, -9 and -8200. The following issues were addressed in -0104 OPS: Input power to SCE drops below 16 volts during battery starts resulting in nuisance SPOILER CONTROL CHANNEL faults. Nuisance ARM and DO NOT ARM output driver faults when SCE system test is run with Auto-Speedbrake 28 VDC circuit breaker open.

In early 2024, an operator reported an aircraft experienced the loss of all flight spoiler after takeoff. Investigation of this report found that for specific BITE test failures combined with another inoperative lane could result in loss of flight spoilers, however there is a delay in illuminating the SPOILERS caution light. The delay in setting the spoiler light was due to software monitoring requiring control wheel input to disable the faulted spoiler panels.

Status

The SCE -0104 OPS has been revised to change the BITE to immediately report loss of flight spoilers. Since the design of the

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

-0104 OPS was complete but not released, this change resulted in a new OPS version, -1104.

Interim Action

In the interim, operators experiencing status message associated with the SCE should use the Onboard Maintenance Function (OMF) and perform the SCE System test (Aircraft Maintenance Manual (AMM) Task 27-61-45-730-801) and any of the other SCE system tests required by the IFIM task associated with the status messages displayed. Other tests include:

AMM Task 27-61-45-730-802 Speedbrake Lever Transducer Test

AMM Task 27-61-45-730-803 First Officer's Wheel Transducer Test

AMM Task 27-61-45-730-804 Ground Spoiler Control Module Replacement Test

AMM Task 27-61-45-730-805 Flight Spoiler Test

Final Action

Boeing will release a Service Bulletin to install SCE OPS version -1104, which will correct the issues identified in this FTD.

Milestones

Root Cause Established: 11 Dec 2019

Solution Selected: 11 Dec 2019

Change Committed: 18 May 2023

Compliance Summary Report (CSR) Approved: 01 July 2026

Systems Safety Analysis (SSA) Approved: 15 July 2026

OPS -1104 Certification Complete: 28 July 2026

Service Bulletin 737-27-1328 Released: 30 July 2026

Production Incorporation: ECD September 2026 Line Number 9802 and on

Note: Target dates are based upon currently available status and have risk of future revision.

Operator Action

Operators should install SCE OPS version -0103 in accordance with Boeing Service Bulletin (SB) 737-27-1309 to mitigate other issues identified with the SCE. If Status Message 27-01000 is reported, Maintenance should use the Onboard Maintenance Function (OMF) and perform the SCE test and any of the other SCE system tests required by the IFIM task associated with the status messages displayed.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Fleet Team Digest Article (FTD)	737MAX-FTD-27-17005		
Fleet Team Digest Article (FTD)	737MAX-FTD-27-17006		
Fleet Team Digest Article (FTD)	737MAX-FTD-27-18001		
Service Related Problem (SRP)	737MAX-SRP-27-0309		

Related Categories

- Flight Deck Effects and Maintenance Messages : Issue that occurs frequently and causes a flight deck effect or maintenance message
- SRPs - Economic : Service Related Problems in work by Boeing that have an economic impact

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991