FLEET TEAM DIGEST

737MAX-FTD-27-19002

Issue Title : Rudder Pedal Restriction due to Cover Fastener Migration

Airplane Model	ATA	Minor Model(s)
737MAX	2721-31	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
01/20/2020	07/23/2020	03/13/2020

Estimated Completion Date	Next Update Date

Revision Description

Updated Description, Final Action, and Milestone sections to reflect that the service bulletin is available, and the Milestones section that parts are available. This closes the issue and FTD.

Applicability

All 737NG and 737MAX aircraft

Description

Boeing has received reports from operators, that fasteners used to attach the rudder pedal shroud assemblies to the upper cover assembly, on both the Captain and the First Officer rudder pedals, had become loose and protruding, resulting in restricted rudder pedal movement. This condition can occur when fasteners are not correctly installed. Our investigation found that incorrectly installed fasteners can occur as a result of limited access and flexing of the shroud assembly.

One Operator reported that the rudder pedal could not reach the forward stop position and a subsequent maintenance inspection revealed that one protruding shroud fastener on First Officer's side was limiting rudder pedal travel. This condition was previously addressed in 2015 by Airworthiness Directive (AD) 2017-14-13 and Service Bulletin (SB) 737-25A1732 for a one-time inspection of the fasteners for LN 1-3555. Boeing also initiated production process monitoring (visual inspection) at LN 3556. A warning was added to the Aircraft Maintenance Manual (AMM) to verify the screws are installed correctly.

There have been a total of 5 fasteners found protruding on airplanes that had either performed the SB or been produced after installation monitoring had been implemented.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Boeing initiated 737NG-SRP-27-0303 to address this condition for the 737NG and 737MAX fleet. As a result of the SRP, Boeing released Service Bulletin 737-27A1313 for 737MAX and Service Bulletin 737-27A1314 for 737NG airplanes.

Status

During the initial kit installation, an operator identified a need to revise SB 737-27A1313. Boeing released multi-operator message MOM-MOM-20-0410-01B detailing the changes expected in the new revisions. Boeing released revision 01 on 24 June 2020.

Interim Action

Since final action has been released, no interim action is necessary.

Final Action

Boeing has released Service Bulletin 737-27A1313 R1 and 737-27A1314 R1.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: 12/13/18

Solution Selected: 02/14/19

Production Incorporation: LN 8083

Service Bulletin Available: 03/18/20

Parts Available: 03/17/20

Service Bulletin Revision Released: 6/24/20

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Related Problem (SRP)	737NG-SRP-27-0303		10/25/2018
Service Related Problem (SRP)	737NG-SRP-27-0274		04/15/2016
Service Bulletin (SB)	737-25-A1732	R2	04/13/2017
Airworthiness Directive (AD)	2017-14-13		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Related Categories

- SRPs - Safety : Service Related Problems in work by Boeing that have an airplane or personal safety impact

Attachments:

a) Rudder Pedal Shround Installation

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991