# FLEET TEAM DIGEST

## 737MAX-FTD-27-22001

**Issue Title :** Elevator Pitot Probe – Flexible Hose Orientation

| Airplane Model | ATA | Minor Model(s) |
|---|---|---|
| 737MAX | 2731-17 | -7, -8, -8200, -9, -BBJ |

| Other Model(s) | ECCN |
|---|---|
| | 9E991 |

| Originated Date | Last Revised Date | Created On |
|---|---|---|
| 04/05/2022 | 04/05/2022 | 04/01/2022 |

| Estimated Completion Date | Next Update Date |
|---|---|
| 12/21/2022 | 06/15/2022 |

## Description

Multiple operators have reported ELEV FEEL DIFF light illumination. During subsequent troubleshooting, operators have found the elevator pitot probe flexible hoses improperly oriented with a low point between the fixed pneumatic lines of the elevator feel system and the pitot probe. A low point in the flexible hose installation allows moisture accumulation which freezes during flight causing a blockage and resulting in the ELEV FEEL DIFF light illumination.

The preliminary investigation at Boeing suggests that during de-preservation activities on Boeing stored 737 MAX airplanes, the elevator pitot probe flexible hoses may have been incorrectly re-installed following elevator pitot probe flushing.

A depiction of both correct and incorrect flexible hose installation is provided in the attachments. These views are from Access Panel 323FL looking forward.

## Status

Boeing is investigating the origins and scope of this issue. The investigation is currently on-going with a expected completion date of mid-April 2022.

## Interim Action

In the event of ELEV FEEL DIFF light illumination, flush the elevator pitot lines per AMM TASK 27-31-17-170-801 and visually inspect the orientation of hoses via Access Panel 323FL to ensure there is a continuous downward slope of the flexible hoses between the fixed pneumatic lines and the elevator pitot probes.

## Final Action

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

# FLEET TEAM DIGEST

Upon completion of the Boeing production investigation, Boeing will release a Service Letter identifying the scope of the potentially affected airplanes and corrective actions.

Boeing will further add elevator pitot flushing recommendations to the IFIM when ELEV FEEL DIFF light illumination occurs. A review of the IFIM as part of this investigation identified the lack of a elevator pitot flushing following an ELEV FEEL DIFF light event..

Boeing will also add a recommendation to the AMM to visually inspect the orientation of the elevator pitot flexible hoses following elevator pitot maintenance via access panel 323FL.

## Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Fleet Team Digest article released to detail issue and planned actions – 5-April (target)

Boeing to complete Quality Investigation – 15-APR (target)

Incorporate flushing guidance in IFIM – 15-APR (target)

Service Letter to be published to formalize fleet impact and recommended actions – 30-APR (target)

Updated AMM procedures to recommend visual verification of pitot probe hose orientation – 15-MAY (target)

## Related Categories

- Airplane Maintenance Issues : Issues that occur during airplane maintenance or have an impact on airplane reliability

## Attachments:

a) Correct Flexible Hose Orientation

b) Incorrect Flexible Hose Orientation

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991