FLEET TEAM DIGEST

737MAX-FTD-27-22002

Issue Title : Un-Commanded Spoiler Motion Due to Wire Riding Condition

Airplane Model	ATA	Minor Model(s)
737MAX	2700-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
07/08/2022	07/13/2023	05/01/2023

Estimated Completion Date	Next Update Date
07/30/2023	07/29/2023

Revision Description

Revision to provide updates on the open SRP and upcoming planned in-service communications, along with compliance time recommendation.

Description

The purpose of this FTD article is to provide updates on the SRP investigation for the 737 MAX issue of uncommanded spoiler motion due to a wire riding condition that was presented at both the May 2022 MAX Fleet Team Meeting and supplemental Out of Sequence calls.

An operator experienced multiple unusual spoiler deployments resulting in un-commanded roll to the right during cruise with the associated SPOILERS fault light illuminating on the P5-3 panel. This issue was noted as intermittent and was observed on multiple flights. Each time the condition occurred, the Spoiler Control Electronics (SCE) issued the fault code: “SPOILER 10 DOES NOT FOLLOW COMMANDED POSITION” (27-01630).

Various troubleshooting attempts resulted in removal of several components, including the Spoiler #10 actuator, the actuator connector, and the SCE Line Replaceable Unit. Supplemental inspections and follow-up lab testing confirmed root cause to be a wire bundle that was damaged as a result of a non-conforming installation between the main wheel well and wing trailing edge. This condition was also previously discovered in production.

Boeing plans to release a service bulletin to incorporate any design changes and further operator action from the completion of the SRP.

Status

27-September-2022: 649/805 (80.62%) of aircraft in MAX fleet inspected. 27 airplanes (4.27%) found to have insufficient

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

clearance. 16 aircraft (2.49%) found to have actual wire riding. Operators advised accordingly on in-service actions taken based on findings.

Updates presented at 9/14 Lead Airline Call posted to Ref/D/ FIX.

28-April-2023: Boeing submitted Service Bulletin 737-27A1325 to FAA for review and approval.

Interim Action

Current Operator Action is to inspect affected aircraft via the inspection guidance outlined in Ref/B/ Service Letter and provide correspondence to Boeing as noted in the Ref/C/ MOM.

Final Action

Final actions to be provided via a Service Bulletin after completion of SRP.

Aircraft Illustrated Parts Catalog (AIPC) to be updated in accordance with any relevant drawing updates.

Boeing anticipates that the FAA will issue an airworthiness directive using the Notice of Proposed Rulemaking (NPRM) process.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: Feb-2022
Solution Selected: 23-May-2022

FAA Review: Boeing received FAA approval for Service Bulletin 737-27A1325 to FAA.
Service Bulletin Available: SB 737-27A1325 RB, ECD - 19-July-2023 (Recommended 36 month compliance time (within calculated risk-based period)).
Parts Available: N/A

Reference Categories

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Type	Reference Number	Revision Number	Reference Date
Multi-Operator Message (MOM)	MOM-MOM-22-0253-01B(R1)		
Service Related Problem (SRP)	737MAX-SRP-27-0328		
Service Letter (SL)	737-SL-27-293-B		
Other	FIX ISS-27-22-40076		

Related Categories

- SRPs - Safety : Service Related Problems in work by Boeing that have an airplane or personal safety impact

Attachments:

a) Images of Wire Riding Condition

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991