FLEET TEAM DIGEST

737MAX-FTD-27-23001

Issue Title : Outboard Ground Spoiler Actuator Fatgiue Failures

Airplane Model	ATA	Minor Model(s)
737MAX	2762-94	-8, -8200, -9, -BBJ

Other Model(s)	ECCN
737NG, 737	9E991

Originated Date	Last Revised Date	Created On
12/10/2024	08/21/2025	08/05/2025

Estimated Completion Date	Next Update Date

Revision Description

Added Final Action Details, References, and Milestone dates.

Description

Boeing has received reports from operators of housing fractures on the Outboard Ground Spoiler Actuators P/N 65C26864-3. Operators have reported a combination of failures on the ground and in flight. This FTD is to capture Boeing's knowledge of this issue, and provide operators with information of the ongoing efforts to address these actuator failures.

Background

Over the past 20 years, operators have reported over 100 events of Outboard Ground Spoiler Actuators failures, where the housing threads were found cracked or separated. These fractures have occurred on the 737CL and NG. No events have yet to occur on the 737 MAX.

These events, in the majority of cases, resulted in a complete loss of the aircrafts hydraulic system A. During normal operation these actuators are engaged during landing, once the aircraft is on the ground, to increase downward force on the wheels leading to greater braking potential. These events have occurred during normal operation, after wheels on-ground, once the Outboard Ground Spoilers are deployed during landing. However, there have been reports where these failures have also occurred in-flight, outside of the intended actuation sequence. This has been attributed to pressure spikes during landing gear extension, or flaps 40 sequence.

The current actuator is P/N 65C26864-3, which was first used during 737 Classic production and has since been incorporated onto the 737NG and 737 MAX. We examined several of the housings and determined that the fractures were the result of fatigue, initiated at various locations on the inside surface of the thread and thread relief area.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Status

Boeing has initiated an SRP on this issue. A design change to revise the thread form to improve fatigue resistance has been completed for the Outboard Ground Spoiler Actuators. In addition, Boeing has developed an NDT procedure to identity cracked actuators on-wing that operators can use to mitigate against in-service events.

As of 8/5/2025, these components are under management control. Over the past year Boeing has increased the spares stock for this part and will continue to do so until a sufficient supply is available to support the fleet.

The investigation into these failures has concluded and 737-SL-27-341 has been published with all suggested operator action.

Interim Action

N/A

Final Action

The new actuator design P/N 65C26864–7 has been incorporated into production on and after L/N 9135, and the in-service fleet can utilize Component Service Bulletin 65C26864-27-01 and CSB Kit P/N 002A0152-1, to convert P/N 65C26864–3 to P/N 65C26864–7. In addition, Boeing will publish a Non-Destructive Testing (NDT) PART 4 - 27-00-02 procedure specific to the Outboard Ground Spoiler Actuator, which utilizes Ultrasonic inspection to identify cracked actuators on-wing that operators can use to mitigate in-service events. Service Letter 737-SL-27-341 has been published to inform operators of this failure mode and to provide Boeing's suggested actions.

Milestones

NOTE: All milestone dates are completed.

SRP Initiated: 2/2/2023

Root Cause Established: 10/5/2022

Solution Selected: 3/20/2022

Change Committed: 9/12/2023

Production Incorporation: L/N 9135

CSB-65C26864-27-01 Available: February 19th 2025

NDT PART 4 - 27-00-02 Procedure Available: July 1st 2025

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Service Letter 737-SL-27-341 Available: August 5th 2025

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Related Problem (SRP)	737NG-SRP-27-0332		
Illustrated Parts Catalog (IPC)	P/N 65C26864-3		
Fleet Team Economic (FTE)	FTE-27-15010		
In-Service Occurrence Report (ISO)	ISE-29-24-45895		
Service Letter (SL)	737-SL-27-341		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Outboard Ground Spoiler Actuator	65C26864-3		

Related Categories

- Aging Airplane Issues : Structural issues or systems wear due to high flight cycles or high flight hours on the airplane
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations
- Fleet Team IdeaXchange : Topic of discussion on the Fleet Team IdeaXchange bulletin board
- Flight Operations : Flight Operations
- SRPs - Economic : Service Related Problems in work by Boeing that have an economic impact

Attachments:

a) Ground Spoiler Housing Separation

b) Ground Spoiler Housing Fracture

c) Outboard Ground Spoiler Actuator Crack

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991