FLEET TEAM DIGEST

737MAX-FTD-27-23003

Issue Title : 737 MAX Enhanced Angle of Attack (eAOA) Program Status

Airplane Model	ATA	Minor Model(s)
737MAX	2732-42	-10, -7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
10/17/2023	04/09/2026	04/08/2026

Estimated Completion Date	Next Update Date
01/01/2027	07/09/2026

Revision Description

No updates.

Description

US Legislation passed Consolidated Appropriations Act, HR2617 ACSAA 116 in December 2022 requires certain safety enhancements to all US based MAX airplanes. This was following the MAX Return to Service efforts when a number of areas associated with AOA integrity were identified. Boeing plans to comply with this US Legislation via the 737 MAX Enhanced Angle of Attack suite of enhancements, available to worldwide operators.

The MAX Return to Service, Certification Management Team (CMT) was overseen by joint regulators of the European Aviation Safety Agency EASA, the National Civil Aviation Agency of Brazil (ANAC), U.S. Federal Aviation Administration (FAA), and Transport Canada Civil Aviation (TCCA). Boeing anticipates guidance to be issued from at least these regulators: CMT, EASA, TCCA, and the United Kingdom Civil Aviation Authority (UKCAA).

Background

Enhanced Angle of Attack (eAOA) is a suite of enhancements for the 737 MAX family to mitigate flight deck effects and thus reduce crew workload associated with angle of attack (AOA) vane faults.

Existing 737 independent federated air data system architecture is maintained and enhanced:

New automated failure detection algorithms (AOA monitors) and fault handling to prevent detected erroneous AOA signal propagation to downstream systems.

New crew-controlled means to inhibit persistent erroneous stick shaker and/or overspeed aural warning.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

New and modified crew procedures, training, and maintenance functions reflecting these new capabilities will be provided.

Status

eAOA is expected to be certified as part of the 737-10 Amended Type Certificate (ATC).

Structural provisions are standard for all production 737 models starting at L/N 8325 (May 2022).

Wiring provisions are standard for all production 737 models starting at L/N 8660 (Nov 2022).

Recently passed ACSAA 116 compliance will require the following:

1. Full production incorporation (-7/-8/-8200/-9) within 1 year of 737-10 ATC

2. Retrofit on all delivered MAX airplanes within 3 years of 737-10 ATC

Boeing is currently working on a detailed implementation plan including:

1. Service Bulletin for wire provisions was released in June-2023

2. Service Bulletin for full eAOA installation will follow -10 ATC

3. The initial parts allocation plan and campaign strategy to comply with legislation requirements.

Interim Action

Boeing recommends completing Phase 1 eAOA provisional wiring installation, Service Bulletin 737-34-3778, in preparation for the subsequent eAOA installation Phases 2 and 3. Phases 1, 2, and 3 are defined in the Final Action section.

Final Action

Boeing is recommending a 3 phased approach to install the full eAOA suite of enhancements cumulating into the installation and activation of the new Overspeed Aural Warning/Stick Shaker (OSA/SS) switches.

Phase 1 pertains to the installation of provisional wiring that will support future installation of the OSA/SS switches. Wiring provisions are standard for all production MAX models starting at Line Number 8325 (May 2022). The wiring provision of Phase 1 is applicable to Line Numbers before 8325 and eAOA Provisional Wiring Boeing Service Bulletin 737-34-3778 was released in June 2023. Structural provisions are standard for all production MAX models starting at Line Number 8325 (May 2022). Also included in the Structural provisions bulletin will be the EFIX impacted air frames Line Number 8325 (May 2022) to 8659 (Nov 2022). The structural provisions of Phase 1 is applicable to Line Numbers before 8660 and Structural Provisions Bulletin PRR3M0279-2 Part K will be released DEC-2024.

Phase 2 focuses on the affected Line Replaceable Units (LRUs) and software updates to enable eAOA suite of enhancements.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

This phase encompasses the core eAOA LRU's including the Stall Management Yaw Damper (SMYD), Air Data Inertial Reference Unit (ADIRU), Enhanced Digital Flight Control System Flight Control Computer (EDFCS FCC), and the MAX Display System Display Processing Computer (MDS DPC) with an Option Selection Software (OSS) that has eAOA *disabled*. This phase also encompasses supporting LRU's that have AOA enhancements including the Digital Flight Data Acquisition Unit (DFDAU), the Onboard maintenance functions (OMF), Onboard Network System and the Network File Server (ONS/NFS).

In Phase 2, each of the core and supporting eAOA affected LRUs can be installed independently of other eAOA software installations. There is no order required or other software interoperability concerns in Phase 2; however, ship sets are required for each applicable eAOA LRU.

Phase 1 and Phase 2 can be completed before, at the same time, or after each other.

Phase 3 cumulates into the final installation required for the Full eAOA status encompassing both software updates and the final portion of wiring to support the new OSA/SS switches. This phase requires that both Phase 1 and Phase 2 be completed before beginning. Step 1 of Phase 3 requires the installation of MDS Block Point 2.0 and an OSS with eAOA *enabled*. This step also requires HGS 6000, if installed, software 2.2. For HUD information, please contact Collins Aerospace RTX. Once step 1 of Phase 3 is completed, the final small amount of wiring to support the new P1-5 and the panel itself containing the INHIBIT switches must be completed.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

The below milestones are for initial planning:

1. Production Wiring, MAY-2022 (Complete)

2. Production Structural Provisions (EFIX Wiring Changes and P18 bracket installation), NOV-2022 (Complete)

3. Wire Install Validation Test, 10-APR-2023 (Complete)

4. Wire Provisions Service Bulletin (737-34-3778) release, 27-JUN-2023 (Complete)

5. Boeing Information Notice (737-34-3778-IN-01), 14-AUG-2023 (Complete)

6. Wire Provisions Service Bulletin (737-34-3778 Rev 1) release, 09-MAY-2024 (Complete)

7. Structural Provisions Service Bulletin (737-34-4193) release, 14-FEB-2025 (Complete)

8. Full eAOA Service Bulletin (737-34-3806) release, TBD

Operator Action

Operators should review this article to receive the latest information on this program. In addition, operators are encouraged to contact their Boeing Field Service Representative for any additional information.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

Boeing also recommends that each operator review their plans to accomplish this modification. All retrofit needs to be completed on all delivered MAX airplanes within 3 years of 737-10 ATC. Boeing expects a Seed program and a warranty claim process and will update operators in a future FTD update.

To assist in the details on this program, high level presentations on this retrofit program can be found on Fleet IdeaXchange (FIX) on the events of the eAOA Working Together Team (WTT) calendar. Boeing can also assist in this review. Initial Boeing contact can be made through your Boeing Field Service Representative or by sending a BCS message using MyBoeingFleet.

Lastly, during execution of the eAOA retrofit program, Boeing encourages operators to provide regular updates on their progress. To assist in this reporting, a standard reporting template will be attached in a future FTD update.

Part Information

Parts Available:

OMF (ONS/NFS): ONS OS 9.1, NFS OMF OSS BCG3F-0MFC-0010, NFS OPC BCG20-U0000-0AJ8 (IMMR) or BCG21-U0000-0AJ9 (3GMMR), NFS OPC BCG52-U0000-09K3 (IMMR) or BCG55-U0000-0AJ9 (3GMMR), NFS ADS OSS BCG2F-U0000-0AJ7

Parts Required, Availability TBD:

SMYD: 285A1010-114

ADIRU: HG2050BD02

P1-5 Panel: 233A2229-4

DFDAU: BCG41-3131-5705

EDFCS (FCC): 2206-COL-AC2-2D (P13.0)

MDS (DPC): COL2F-0078-010 (BP2.0) OSS eAOA disable, MDS (DPC) COL2F-0078-010 (BP2.0) OSS eAOA enabled

HGS-6000: SW Ops Phase 2.2 (Collins STC)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Affected Documents

AMM 27-31-20, 27-32-00, 34-16-00, 34-21-00

WDM 27-32-11, 27-32-21, 34-16-11, 34-16-21

SSM 27-32, 34-16

SDS 27-32, 34-16

FIM 27-32, 34-16

FCOM/QRH Section 10 (Airspeed Unreliable, AOA FAIL), Section 15 (OVRSPD/STALL WARN INHIB)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Bulletin (SB)	737-34-3778	Rev 1	05/09/2024
Production Revision Record (PRR)	3M0279-2		
Service Bulletin (SB)	737-46-1029		03/16/2023
Service Bulletin (SB)	737-31-2114		04/26/2023
Service Bulletin (SB)	737-34-3806		
Airplane Configuration Bulletin (ACB)	2023-ACB-0003-ATA-31-60		04/06/2023
Service Bulletin (SB)	737-46-1054		03/31/2023
Multi-Operator Message (MOM)	MOM-MOM-23-0498-01B		08/21/2023
Service Bulletin (SB)	737-22A1382		
Service Bulletin (SB)	737-31-1929		
Service Bulletin (SB)	737-34-4097		
Airplane Configuration Bulletin (ACB)	2023-ACB-005-1	Rev 1	06/30/2023
Production Revision Record (PRR)	3M0279-1		05/31/2022
Production Revision Record (PRR)	3M0180		
Production Revision Record (PRR)	3M8275-10S		
Production Revision Record (PRR)	3M0201		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Related Categories

- Flight Operations : Flight Operations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991