FLEET TEAM DIGEST

737MAX-FTD-28-19001

Issue Title : INTRODUCTION OF NEW FUEL QUANTITY PROCESSOR UNIT (FQPU)

Airplane Model	ATA	Minor Model(s)
737MAX	2841-81	-7, -8, -8200, -9, -BBJ
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
08/12/2019	09/09/2021	09/03/2021
Estimated Completion Date	**Next Update Date**	

Revision Description

Added FAA AD.

Updated Milestones section. Project is now closed.

Description

This FTD article is to inform airline operators of the new Fuel Quantity Processor Unit (FQPU) Part Number (P/N) 30128-06 (or P/N 30128-58 for airplanes with auxiliary body fuel tanks). The new FQPU addresses a non-compliant condition on the 737 MAX. During refueling, the new FQPU changed the fuel quantity at which the right-main tank refuel indicator flashes to indicate a failure of the fuel shutoff means. Note: the 737NG airplanes were in compliance.

The root cause is that the set point in the FQPU software at which an auto-shutoff failure would be detected was at a level that, given possible tolerance stack up, could allow fuel to enter the surge tank prior to detection, thus preventing required indication of a refuel system automatic shutoff failure.

In addition to the change in FQPU P/N, the bond between the FQPU and the mounting plate is changed from BAC5117-6 Category 2 to BAC5117-6 Category 8. This change uses non-hardening Corrosion Inhibiting Compound (CIC) in place of sealant BMS5-45 or BMS5-95. This change improves the ease of FQPU installation and reduces the chance of damaging the FQPU or the mounting plate when replacing the FQPU. Beginning with Line Number (LN) 7346, production incorporated this change for 737 MAX. Boeing Service Bulletin (SB) 737-28-1363 includes this change for in-service 737 MAX.

The FAA issued an AD 2021-12-13 for 737 MAX prior to LN 7346 to require replacement:

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

- Old FQPUs P/N 30128-05 with new P/N 30128-06 LN 5602-7345, 737 MAX only.
- Old FQPUs P/N 30128-57 with new P/N 30128-58 (for airplanes with auxiliary body fuel tanks) 737 MAX only IGW/BBJ.

Status

- Boeing SB 737-28-1363 released 2 June 2020 for 737 MAX only.
- No retrofit plan for 737NG. Attrition basis only (NG Fuel Gauging Software is unchanged from the 30128-04 FQPU)
- IPC 28-41-81-01 has been updated reflecting interchangeability.
- AMM updated to address processor installation issue, 15 Jan 2021 revision.
- Supplier has completed updating the CMM.
- The CMM has been approved by the FAA.

Interim Action

None.

Final Action

Boeing Action:

Publish Boeing SB 737-28-1363.

Supplier Collins Aerospace actions:

1. Publish CMM 28-41-99 and 28-42-04 for 737 MAX.
2. Publish CMM 28-41-73 and 28-41-87 for 737NG.
3. Publish the Supplier Service Bulletin (SSB) 30128-28-01 with instructions to modify:

- FQPU P/N 30128-05 into 30128-06.
- FQPU P/N 30128-57 into 30128-58.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

1. Production Incorporation: LN 7650 (Complete)
2. FQPU removal tool definition, 30 Aug 2019 (Complete). Removal tool definition will be provided in the SB for operators to locally fabricate or use their own tool.
3. AMM TASK 28-41-81-000-801 FQPU removal update: 15 Jan 2021 (Complete)
4. Boeing SB 737-28-1363 published, 2 June 2020 (Complete)
5. Supplier SB 30128-28-01 published (Complete)
6. Supplier CMM's published, 30 Aug 2021 (Completed)
7. FAA released AD 2021-12-13, effective date 29 July 2021 (Completed)

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Operator Action

Airline/Operator Action for the 737 MAX:

- Incorporate the Boeing SB to replace the old with the new FQPU, or
- Send the 30128-05/-57 processor to supplier Collins to be modified into a 30128-6/-58 processor. Refer to the VSB 30128-28-01 for detail.

Compliance:

- Boeing recommends accomplishment on affected airplanes within 5 years of the release date of the Boeing Service Bulletin.
- The service bulletin compliance time of 5 years will allow sufficient time for operator planning, scheduling and accomplishment of the retrofit within the risk-based control program time determined by the FAA Transport Airplane Risk Analysis methodology.

Part Information

Interchangeability:

The new FQPU PN 30128-06 is:

-One way interchangeable with -05 on 737 MAX LNs 5602-7345

-Two way interchangeable with -04 on 737NG LNs 5329, 5411-7348

The new FQPU PN 30128-58 is:

-One way interchangeable with -57 on 737 MAX IGW / BBJ

-Two way interchangeable with -56 on 737NG IGW / BBJ

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Service Related Problem (SRP)	737MAX-SRP-28-0201	-	06/13/2019
Production Revision Record (PRR)	3M0167	Q	02/08/2019
Fleet Team Safety (FTS)	ISS-28-19-27869		07/22/2019

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FQPU with aux tank (old)	S345A001-017	Collins Aerospace	30128-56
FQPU with Aux Tank (new)	S345A001-051	Collins Aerospace	30128-58
FQPU (old)	S345A001-040	Collins Aerospace	30128-05
FQPU with aux tank (old)	S345A001-050	Collins Aerospace	30128-57
FQPU (old)	S345A001-013	Collins Aerospace	30128-04
Fuel Quantity Processor Unit (FQPU) (new)	S345A001-041	Collins Aerospace	30128-06

Related Categories

- Regulatory : Issues mandated by airworthiness directive or other regulatory guidance material

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991