FLEET TEAM DIGEST

737MAX-FTD-28-20001

Issue Title : MISIDENTIFICATION OF P/N 60-755100-5 FUEL PUMPS BUILT IN 2006

Airplane Model	ATA	Minor Model(s)
737MAX	2800-00	-7, -8, -8200

Other Model(s)	ECCN
737NG	9E991

Originated Date	Last Revised Date	Created On
01/05/2023	09/01/2026	05/15/2026

Estimated Completion Date	Next Update Date
12/19/2026	10/31/2026

Revision Description

Updated Applicability Section.

Applicability

Pumps with incorrect labels may have been originally installed on 737NG production airplanes delivered in 2006 and early 2007 including, but not limited to line numbers (L/N): 1953, 1987, 1990, 1991, 1993, 1996, 1999, 2001, 2006, 2008, 2011, 2012, 2012, 2013, 2113, 2115, 2117, 2119, 2120, 2121, 2123, and 2153.

The pump Part Number (P/N) 60-755100-5 is used on the 737NG, 737 MAX, 747-100 / -200 / -300 and 757 -200 / -300. The pump P/N 60-75503-5 is used on the 747-100 / -200 / -300 only.

Note: This issue is not directly applicable to the 737 MAX. However, since the subject pump part number is shared across models, the issue could potentially affect the MAX depending on how operators manage their spare parts.

Description

In 2006, the supplier Crane A&E delivered P/N 60-755100-5 Pumps to Boeing with a misidentified part number on the identification plate. The plate was marked as “P/N 60-77503-5” when it should have been marked as “P/N 60-755100-5.” These pumps were installed on production aircraft in 2006 and early 2007. Note - Please see attachment for depiction of pump and incorrect label.

Background

In 2006, twenty-three (23) fuel boost pumps installed on production aircraft may have had misidentified P/N on their identification plates. Two operators reported the issue to Boeing in 2012 and 2018. Boeing opened a quality Investigation in 2018. The investigation determined that the pump supplier, Crane A&E, had experienced a label handling mix-up during their pump assembly process. Crane further identified the following population of pumps with the misidentified part numbers: Pumps with Serial Numbers 040634189 through 040634201 and 090635240 through 090635249. Crane is developing a supplier Service Bulletin (SB) which intends to allow discrepant labels be corrected by operators. A release date for this SB is yet to be determined. An

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

inspection for discrepant labels can be performed during the normal course of maintenance. The P/N 60-755100-5 Pump, if incorrectly labeled as “P/N 60-75503-5,” will not physically fit into the interface (housing) for a P/N 60-75503-5 pump.

Status

Boeing is working with Crane to release a supplier SB which will allow discrepant labels to be corrected by operators.

Interim Action

Contact Crane A&E if a discrepant pump label is found.

Final Action

If a Fuel Boost Pump Impeller Motor is found misidentified, replace the identification plate per the Crane A&E SB (not yet published).

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Issue Identified: 2018

Supplier SB Available: 4th Qtr. 2026 (Target)

Operator Action

Replace Fuel Boost Pump Impeller Motor, part number identification plate during the normal course of maintenance, per Crane A&E SB. In addition, operators can return the serviceable Fuel Boost Pump Motor-Impeller Sub-Assembly to Hydro-Aire Inc, address, Repair and Overhaul, Crane A&E, Hydro-Air Inc., 3000 Winona Blvd., Burbank, CA, 91510-7722, USA. The reconfiguration of the Fuel Boost Pump Motor-Impeller Sub-Assembly will be done by Hydro-Aire, Inc. or an approved repair station.

Part Information

Correct P/N: 60-755100-5

Mislabeled P/N: 60-75503-5

Affected Documents

Crane A&E, Hydro-Aire, Inc. Component Maintenance Manual (CMM) 28-22-08, Revision 5, for Fuel Boost Pump Motor-Impeller Subassembly, Part Number 60-755100-2, -4, and -5.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Supplier Information

Commercial Spares

Crane A&E

Hydro-Aire, Inc.

3000 Winona Ave

Burbank, Ca 91504

www.craneae.com

1-818-526-2481

1-818-526-2500

Related Categories

- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- Manufacturing Quality Issues : Issues related to airplane or component manufacturing quality

Attachments:

a) Fuel Pump Data Label Illustratioins

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991