FLEET TEAM DIGEST

737MAX-FTD-28-22003

Issue Title : 737MAX APU Fuel Feed Line Shroud On-Wing Repair

Airplane Model	ATA	Minor Model(s)
737MAX	2825-00	-8, -9
Other Model(s)	**ECCN**	
	9E991	

Originated Date	Last Revised Date	Created On
10/18/2022	05/18/2023	04/20/2023
Estimated Completion Date	**Next Update Date**	
03/27/2024	09/27/2023	

Revision Description

The Status and Milestone sections were updated.

Description

Multiple 737 operators have experienced damage to the Auxiliary Power Unit (APU) fuel feed line shroud. Currently, shroud damage can only be addressed by removing and replacing the damaged shroud with a new shroud or by repairing the shroud per CMM 28-00-10. Both options require removal of the damaged shroud. Due to the extensive time required to remove and reinstall the shroud, Boeing is evaluating an on-wing repair.

Status

Boeing is evaluating an APU fuel line shroud on-wing repair that could be performed as an alternate to CMM 28-00-10 repair options. The repair would entail fabricating and installing an aluminum doubler to wrap around the damaged portion of the shroud. This option is in engineering development and, if qualified, would allow for an on-wing permanent repair that would take significantly less time to perform compared to removing and replacing an APU fuel line shroud. Boeing is presently developing a test plan to gather all necessary data for substantiating the proposed repair.

Boeing initiated certification testing in Dec 2022 in order to test the repair to the design proof pressure of 240 psi. After the initial testing, the repair had failed the pressure test at 160/170 psi. Boeing is re-evaluating the limits required for the repair pressure certification test. Stress and load testing to simulate hard landing and turbulence conditions will also be performed once the testing evaluation is complete.

Interim Action

If a damaged APU fuel feed line shroud is found, refer to AMM 28-22-15-700-801 to disposition tube damage.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Final Action

If the on-wing repair option is approved, operators could consider performing the on-wing wrap around repair option to address APU feed line shroud damage.

Boeing will update Alert SB 737-38A1073 to include the approved on-wing repair option.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Proof of Concept Lab Testing: May 2022 (Completed)

Boeing Engineering Test Validation: December 2023 (Ongoing)

FAA Cert. Plan Approval: December 2023 (Target)

Final Boeing Approval of Certification Test Results: December 2023 (Target)

FAA Service Bulletin Approval (SB 737-38A1073): 1Q2024 (Target)

737NG/MAX AMM updated for On-Wing Repair: 1Q2024 (Target)

Reference Categories

Reference Type	Reference Number	Revision Number	Reference Date
Aircraft Maintenance Manual (AMM)	AMM 28-22-15-700-801		
Component Maintenance Manual (CMM)	28-00-10		
Service Related Problem (SRP)	737NG-SRP-28-0230		

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Related Categories

- SRPs - Safety : Service Related Problems in work by Boeing that have an airplane or personal safety impact

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991