FLEET TEAM DIGEST

737MAX-FTD-28-25004

Issue Title : Low Time Part Number (PN) MA30A1017 Actuator Removals

Airplane Model	ATA	Minor Model(s)
737MAX	2800-00	-10, -7, -8, -8200

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
09/18/2025	10/02/2026	08/12/2026

Estimated Completion Date	Next Update Date
12/18/2026	11/14/2026

Revision Description

The Background and Milestones sections of this FTD has been updated.

Description

Operators have reported an increasing number of low time removals of actuator P/N MA30A1017 when troubleshooting spar valve close light and crossfeed valve open position light indicator faults. Removal and replacement of the actuator generally clears the fault. The Original Equipment Manufacturer (OEM) for P/N MA30A1017 is ITT.

Background

Actuator P/N MA30A1017 is installed on both the 737NG and 737MAX for both spar valve and crossfeed valve positions. It is electrically operated and provides a position output indication at connector pin 3. A manual override arm is also provided for direction indication of the actuator's position. See CMM 28-20-25 for more details on the actuator.

The P5-2 fuel system module has position indication for the SPAR VALVE CLOSED blue lights. Normal indication logic is:

- Valve closed > indication dim blue light
- Valve open > indication off
- During a transition or when the valve command and actual position disagree > indicator bright blue light

Operators have reported faults in which the spar valve close light remains bright when the actuator's override lever arm has visually reached the fully open or fully closed position, indicating a persistent command/position indication disagree.

Operators have reported similar faults for the crossfeed valve open. The crossfeed VALVE OPEN light indication is similar but opposite of the spar valve.

- Valve closed > indicator off
- Valve open > indicator dim blue light
- During a transition or when the valve commanded and actual position disagree > indicator bright blue light

Operators have reported faults in which the crossfeed valve open indicator light remains bright when the actuator's override lever arm has visually reached the fully open or fully closed position, indicating a persistent command/position indication disagree.

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

In addition, the P/N MA30A1017 actuator is common to the 737NG, 757, 767 and 777 aircraft models. However, these models have reported far fewer failure events. Corrective action for this issue on other models will be considered pending its resolution on the 737 MAX.

Status

Boeing's Equipment Quality Analysis (EQA) lab and ITT's Engineering Group independently tested and evaluated multiple actuators deemed No Fault Found (NFF) by ITT functional testing.

- Normal sequence: as the actuator drives the output shaft to the commanded position, the position-indication circuit asserts first (signaling that the commanded position is reached) then motor drive power is terminated to stop further shaft movement.

- Observed issue: affected actuators have a very small output shaft angle margin between assertion of the indication circuit and motor power termination.

Boeing's EQA lab analysis has completed. The analysis identified this issue is resulting from degrading position indication circuity performance on the actuator's circuit card assembly.

Boeing and ITT are currently reviewing lab findings and fleet returns data for Solution Selection. Solution selection is still being finalized between Boeing and ITT. Once determined, the implementation plan will be provided in this FTD article.

Interim Action

ITT is proactively replacing the circuit card assembly and optical vane on in-warranty units that were returned, tested as No Fault Found (NFF), and exhibit the small output shaft angle margin.

Final Action

A final action has not been determined at this time. However, if the actuator (P/N MA30A1017) is removed due to a spar valve close light or crossfeed valve open position light indicator fault, the unit should be returned to ITT for repair.

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Boeing EQA Lab Analysis: Feb 2026 (Complete)

Fault Mode Characterization Feb 2026 (Completed)

ITT Review of data with Boeing: Apr 2026 (Completed)

ITT and Boeing Solution Selection: To Be Determined

Reference Categories

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Reference Type	Reference Number	Revision Number	Reference Date
Component Maintenance Manual (CMM)	CMM 28-20-25		
Aircraft Maintenance Manual (AMM)	SUBTASK 28-22-00-720-002		

Parts List

Part Name	Boeing Part Number	Supplier Name	Supplier Number
Motor Operated Valve Actuator	S343T003-76	ITT	MA30A1017

Related Categories

- AOGs : Events that cause a significant Airplane On Ground (AOG) condition
- Component Issues : Issues that occur during component maintenance or have an impact on component reliability
- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991