FLEET TEAM DIGEST

737MAX-FTD-29-21001

Issue Title : 737 MAX ACMP Circuit Breaker Tripping

Airplane Model	ATA	Minor Model(s)
737MAX	2900-00	-7, -8, -8200, -9, -BBJ

Other Model(s)	ECCN
	9E991

Originated Date	Last Revised Date	Created On
07/28/2022	02/08/2024	02/07/2024

Estimated Completion Date	Next Update Date
05/13/2025	07/29/2024

Revision Description

Milestones updated per supplier schedule.

Applicability

737 MAX Airplanes

Description

Boeing has received reports of Alternating Current Motor Pump (ACMP), also called Electric Motor Driven Pump (EMDP), circuit breaker (C/B) tripping during pre-flight ground operation. C/B trips:

- may occur on all 737 models with the Parker pump configuration
- are unpredictable and not isolated to certain airlines,
- are not temperature dependent and not limited to the first start of the day,
- negatively affect dispatch reliability, especially for the 737NG and 737 MAX, due to the C/B location in the EE bay.

Status

The ACMP manufacturer has performed analysis and some engineering testing that showed the tripping problem could be associated with low voltage at the ACMP terminals and stalling of the pump motor.

Analysis and engineering test data from the ACMP manufacturer has been reviewed by Boeing. Boeing has initiated a Service Related Problem (SRP) to determine root cause and evaluate potential solutions.

Boeing has evaluated the project plan from the supplier with respect to the proposed rotor optimization redesign and have

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

provided project milestones below.

Engineering validation testing during the 3-phase testing experienced a failure. Parker has been working on Design Failure Mode Effects Analysis (DFMEA) and Process Failure Modes and Effects Analysis (PFMEA).

Interim Action

737 MAX ACMP circuit breakers are located in the EE bay and would require maintenance personnel to reset the circuit breakers.

Final Action

Release of Parker Service Bulletin 4Q2024 (Target)

Milestones

Note: Target dates are based upon currently available status and have risk of future revision.

Root Cause Established: Yes

Change Committed: 01/23/2018 (Complete)

Solution Selected: 05/16/2018 (Complete)

Compliance Matrix: 06/26/2018 (Complete)

Design Review: 2/17/2023 (Complete)

Qualification Start: January, 2025 (Target)

Certification Approval: July, 2025 (Target)

Parts Available: 3Q2025 (Target)

Production Incorporation: 3Q2025 (Target)

Service Bulletin Available: 3Q2025 (Target)

Parts List

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991

FLEET TEAM DIGEST

Part Name	Boeing Part Number	Supplier Name	Supplier Number
ACMP	10-60556-30		57186-10

Related Categories

- Dispatch Reliability Issues : Issues that cause revenue flight delays and cancellations
- Flight Operations : Flight Operations

BOEING PROPRIETARY - The information contained herein is Proprietary to The Boeing Company and shall not be reproduced or disclosed in whole or in part or used for any reason except when such user possesses direct, written authorization from The Boeing Company. Encrypted emails required for forwarding via Email.The document generated on 11/05/2026 by Fleet Team Digest application via MyBoeingFleet. This document is for reference purposes only, visit the application for all the latest and updated revisions of this document.

Copyright ©2026 Boeing. All rights reserved.

EXPORT CONTROLLED -This technology or software is subject to the U.S. Export Administration Regulations (EAR), (15 C.F.R. Parts 730-774). No authorization from the U.S. Department of Commerce is required for export, re-export, in-country transfer, or access EXCEPT to country group E:1 or E:2 countries/persons per Supp.1 to Part 740 of the EAR. ECCN : 9E991