PTF ALL

Maintenance Message 21-30011 - Fault Isolation

WIRING FROM CPC-2 TO CABIN PRESSURE SELECTOR PANEL HAS A FAULT
DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-2

CORRECTIVE ACTION SUMMARY

Repair Wiring D10726-D10740B
Repair Wiring D10726-D10740A
Repair Wiring Circuit Breaker C1271-D10740C
Repair Wiring Circuit Breaker C1272-D10724

A. Description

(1) This task is for this maintenance message:
  (a) WIRING FROM CPC-2 TO CABIN PRESSURE SELECTOR PANEL HAS A FAULT

(2) This fault can occur because of the failure of the wiring from CPC-2 to the cabin pressure selector panel.

B. Initial Evaluation

(1) Do this task:
- Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Do this check of the wiring:
  (a) Disconnect connector D10726 from the cabin pressure control module, P5-6.
  (b) Remove the cabin pressure controller 2, M1654. This is the task:
    - Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801.
  (c) Do a wiring check between these pins of connector D10726 at the cabin pressure control module and these pins of connector D10740B at the E1-1 rack (WDM 21-31-11, WDM 21-31-23):

D10726		D10740B
pin 28	.....	pin A7
pin 29	.....	pin A8
pin 8	.....	pin B3
pin 9	.....	pin B7

  (d) Do a wiring check to make sure that pin 18 of D10726 has continuity to ground.
  (e) Do a wiring check to make sure that pin 30 of D10726 has continuity to ground.
  (f) If you find a problem with the wiring, then do these steps:
    1) Repair the wiring.
    2) Re-connect connector D10726 to the cabin pressure control module, P5-6.
    3) Re-install the cabin pressure controller 2, M1654. This is the task:
      - Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
    4) Do the AMM test that you did at the start of this task.
    5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.
  (g) If you do not find a problem with the wiring, then continue.

(2) Do this check of the wiring:

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

(a) Do a wiring check between these pins of connector D10726 at the cabin pressure control module and these pins of connector D10740A at the E1-1 rack (WDM 21-31-23):

D10726		D10740A
pin 16	.....	pin A1
pin 17	.....	pin A2
pin 19	.....	pin D15

(b) If you find a problem with the wiring, then do these steps:
1) Repair the wiring.
2) Re-connect connector D10726 to the cabin pressure control module, P5-6.
3) Re-install the cabin pressure controller 2, M1654. This is the task:
• Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
4) Do the AMM test that you did at the start of this task.
5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(c) If you do not find a problem with the wiring, then continue.

(d) Re-connect connector D10726 to the cabin pressure control module, P5-6.

(3) Do this check of the wiring:

(a) Open the PRESSURIZATION CONTROL AUTO 2 circuit breaker, C1271 [P6-4, F5].

(b) Do a wiring check between this terminal of circuit breaker C1271 and this pin of connector D10740C at the E1-1 rack (WDM 21-31-23):

C1271		D10740C
term =L	.....	pin 3

(c) Do a wiring check to make sure that pin 2 of D10740C has continuity to ground.

(d) If you find a problem with the wiring, then do these steps:
1) Repair the wiring.
2) Close the PRESSURIZATION CONTROL AUTO 2 circuit breaker, C1271 [P6-4, F5].
3) Re-install the cabin pressure controller 2, M1654. This is the task:
• Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
4) Do the AMM test that you did at the start of this task.
5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(e) If you do not find a problem with the wiring, then continue.

(f) Close the PRESSURIZATION CONTROL AUTO 2 circuit breaker, C1271 [P6-4, F5].

(g) Re-install the cabin pressure controller 2, M1654. This is the task:
• Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

(4) Do this check of the wiring:

(a) Open the PRESSURIZATION CONTROL IND circuit breaker, C1272 [P6-4, F7].

(b) Disconnect connector D10724 from the cabin pressure control module, P5-6.

(c) Do a wiring check between this terminal of circuit breaker C1272 and this pin of connector D10724 at the cabin pressure control module (WDM 21-31-23):

C1272		D10724
term =L	.....	pin 16

(d) Do a wiring check to make sure that pin 29 of D10724 has continuity to ground.

(e) If you find a problem with the wiring, then do these steps:
1) Repair the wiring.
2) Close the PRESSURIZATION CONTROL IND circuit breaker, C1272 [P6-4, F7].
3) Re-connect connector D10724 to the cabin pressure control module, P5-6.
4) Do the AMM test that you did at the start of this task.

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details