PTF ALL

Maintenance Message 21-30260 - Fault Isolation

SMYD-1 ARINC 429 RCVR SIGNAL IS INVALID

DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-1

CORRECTIVE ACTION SUMMARY

Cycle SMYD-1 CMPTR DC Circuit Breaker
Correct Related Maintenance Messages
Repair Wiring D3683A-D10738B
Replace Stall Management/Yaw Damper Computer 1 [M1747]

A. Description

(1) This task is for this maintenance message:
  (a) SMYD-1 ARINC 429 RCVR SIGNAL IS INVALID

(2) This fault can occur because of the stall management/yaw damper computer 1 ARINC 429 receiver signal is an invalid.

B. Initial Evaluation

(1) Do this task:
- Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Open and then close this circuit breaker: C1204, SMYD-1 CMPTR DC [P18-2, E5].
  (a) Do the AMM test that you did at the start of this task.
  (b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.
  (c) If the OMF shows ACTIVE for the maintenance message, then continue.

(2) Look in OMF Existing Faults, 27 Flight Controls Stall Management Yaw Damper System for maintenance messages related to the stall management/yaw damper computer 1, M1747.
  (a) If you find any related maintenance messages, then do these steps:
    1) Do the fault isolation task for each related maintenance message.
    2) Do the AMM test that you did at the start of this task.
    3) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.
  (b) If you do not find related maintenance messages, then continue.

(3) Do this check of the wiring:
  (a) Remove the stall management/yaw damper computer 1, M1747. This is the task:
    - Stall Management Yaw Damper (SMYD) Removal, AMM TASK 27-32-42-000-801.
  (b) Remove the cabin pressure controller 1, M1653. This is the task:
    - Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801.
  (c) Do a wiring check between these pins of connector D3683A at the E3-2 rack and these pins of connector D10738B at the E2-2 rack (WDM 21-31-24, WDM 27-32-12):

D3683A		D10738B
pin 95	.....	pin A5
pin 94	.....	pin A6

  (d) If you find a problem with the wiring, then do these steps:
    1) Repair the wiring.

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

2) Re-install the stall management/yaw damper computer 1, M1747. This is the task:
   - Stall Management Yaw Damper (SMYD) Installation, AMM TASK 27-32-42-400-801.
3) Re-install the cabin pressure controller 1, M1653. This is the task:
   - Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
4) Do the AMM test that you did at the start of this task.
5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(e) If you do not find a problem with the wiring, then continue.

(f) Re-install the cabin pressure controller 1, M1653. This is the task:
   - Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

(4) Install a new stall management/yaw damper computer 1, M1747. To install it, do this task:
   - Stall Management Yaw Damper (SMYD) Installation, AMM TASK 27-32-42-400-801.

(a) Do the AMM test that you did at the start of this task.

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details