PTF ALL

Maintenance Message 21-30291 - Fault Isolation

N1 OR N2 SIGNAL FROM SMYD-1 OR SMYD-2 IS INVALID
DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-2

CORRECTIVE ACTION SUMMARY

Correct Related Maintenance Messages
Repair Wiring D3683A-D10740B
Repair Wiring D3685A-D10740B
Replace Stall Management/Yaw Damper Computer 1 [M1747]
Replace Stall Management/Yaw Damper Computer 2 [M1748]

A. Description

(1) This task is for this maintenance message:
(a) N1 OR N2 SIGNAL FROM SMYD-1 OR SMYD-2 IS INVALID

B. Initial Evaluation

(1) Do this task:
- Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Look in OMF Existing Faults, 27 Flight Controls Stall Management Yaw Damper System for related maintenance messages.
(a) If you find any related maintenance messages, then do these steps:
1) Do the fault isolation task for each related maintenance message.
2) Do the AMM test that you did at the start of this task.
3) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.
(b) If you do not find related maintenance messages, then continue.

(2) Do this check of the wiring:
(a) Remove the stall management/yaw damper computer 1, M1747. This is the task:
- Stall Management Yaw Damper (SMYD) Removal, AMM TASK 27-32-42-000-801.

(b) Remove the cabin pressure controller 2, M1654. This is the task:
- Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801.

(c) Do a wiring check between these pins of connector D3683A at the E3-2 rack and these pins of connector D10740B at the E1-1 rack (WDM 21-31-24, WDM 27-32-12):

D3683A		D10740B
pin 95	.....	pin A5
pin 94	.....	pin A6

(d) If you find a problem with the wiring, then do these steps:
1) Repair the wiring.
2) Re-install the stall management/yaw damper computer 1, M1747. This is the task:
- Stall Management Yaw Damper (SMYD) Installation, AMM TASK 27-32-42-400-801.
3) Re-install the cabin pressure controller 2, M1654. This is the task:
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
4) Do the AMM test that you did at the start of this task.

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(e) If you do not find a problem with the wiring, then continue.

(f) Re-install the stall management/yaw damper computer 1, M1747. This is the task:
- Stall Management Yaw Damper (SMYD) Installation, AMM TASK 27-32-42-400-801.

(3) Do this check of the wiring:

(a) Remove the stall management/yaw damper computer 2, M1748. This is the task:
- Stall Management Yaw Damper (SMYD) Removal, AMM TASK 27-32-42-000-801.

(b) Do a wiring check between these pins of connector D3685A at the E3-2 rack and these pins of connector D10740B at the E1-1 rack (WDM 21-31-24, WDM 27-32-22):

D3685A		D10740B
pin 95	.....	pin A13
pin 94	.....	pin A14

(c) If you find a problem with the wiring, then do these steps:

1) Repair the wiring.

2) Re-install the stall management/yaw damper computer 2, M1748. This is the task:
- Stall Management Yaw Damper (SMYD) Installation, AMM TASK 27-32-42-400-801.

3) Re-install the cabin pressure controller 2, M1654. This is the task:
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

4) Do the AMM test that you did at the start of this task.

5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(d) If you do not find a problem with the wiring, then continue.

(e) Re-install the stall management/yaw damper computer 2, M1748. This is the task:
- Stall Management Yaw Damper (SMYD) Installation, AMM TASK 27-32-42-400-801.

(f) Re-install the cabin pressure controller 2, M1654. This is the task:
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

(4) Replace the stall management/yaw damper computer 1, M1747. These are the tasks:
- Stall Management Yaw Damper (SMYD) Removal, AMM TASK 27-32-42-000-801,
- Stall Management Yaw Damper (SMYD) Installation, AMM TASK 27-32-42-400-801.

(a) Do the AMM test that you did at the start of this task.

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(c) If the OMF shows ACTIVE for the maintenance message, then continue.

(5) Replace the stall management/yaw damper computer 2, M1748. These are the tasks:
- Stall Management Yaw Damper (SMYD) Removal, AMM TASK 27-32-42-000-801,
- Stall Management Yaw Damper (SMYD) Installation, AMM TASK 27-32-42-400-801.

(a) Do the AMM test that you did at the start of this task.

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details