PTF ALL

Outflow Valve Position Indicator Does Not Move or Not Constant - Fault Isolation

CORRECTIVE ACTION SUMMARY

Correct Related Maintenance Messages
Repair Wiring D10724-D10728
Repair Wiring D10724-D10730
Replace Cabin Pressure Control Module [P5-6]
Replace Cabin Pressure Outflow Valve [V48]

A. Description

(1) This task is for this observed fault:

(a) Outflow valve position indicator: does not move or not constant.

B. Initial Evaluation

(1) For the cabin pressure outflow valve, V48, do this task:

- Pressurization System Manual Mode Test, AMM TASK 21-31-00-710-801.

(a) If the system does not operate as specified in the AMM task, then do the Fault Isolation Procedure below.

(b) If the system operates as specified in the AMM task, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Look in OMF Existing Faults, 21 Cabin Pressure for related maintenance messages.

(a) If you find any related maintenance messages, then do these steps:

1) Do the fault isolation task for each related maintenance message.

2) Do the AMM test of the cabin pressure outflow valve that you did at the start of this task.

3) If the system operates as specified in the AMM task, then you corrected the fault.

(b) If you do not find related maintenance messages, then continue.

(2) Do this check of the wiring:

(a) Disconnect connector D10724 from the cabin pressure control module, P5-6.

(b) Disconnect connector D10728 from the cabin pressure outflow valve, V48.

(c) Do a wiring check between these pins of connector D10724 at the cabin pressure control module and these pins of connector D10728 at the cabin pressure outflow valve (WDM 21-31-11):

D10724		**D10728**
pin 18	.....	pin F
pin 30	.....	pin H
pin 31	.....	pin G

(d) If you find a problem with the wiring, then do these steps:

1) Repair the wiring.

2) Re-connect connector D10724 to the cabin pressure control module, P5-6.

3) Re-connect connector D10728 to the cabin pressure outflow valve, V48.

4) Do the AMM test of the cabin pressure outflow valve that you did at the start of this task.

5) If the system operates as specified in the AMM task, then you corrected the fault.

(e) If you do not find a problem with the wiring, then continue.

(f) Re-connect connector D10728 to the cabin pressure outflow valve, V48.

(3) Do this check of the wiring:

(a) Disconnect connector D10730 from the cabin pressure outflow valve, V48.

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

(b) Do a wiring check between these pins of connector D10724 at the cabin pressure control module and these pins of connector D10730 at the cabin pressure outflow valve (WDM 21-31-11):

D10724		**D10730**
pin 25	.....	pin A
pin 24	.....	pin B

(c) Do a wiring check to make sure that pin 28 of D10724 has continuity to ground.

(d) Do a wiring check to make sure that pin D of D10730 has continuity to ground.

(e) If you find a problem with the wiring, then do these steps:

1) Repair the wiring.

2) Re-connect connector D10724 to the cabin pressure control module, P5-6.

3) Re-connect connector D10730 to the cabin pressure outflow valve, V48.

4) Do the AMM test of the cabin pressure outflow valve that you did at the start of this task.

5) If the system operates as specified in the AMM task, then you corrected the fault.

(f) If you do not find a problem with the wiring, then continue.

(g) Re-connect connector D10730 to the cabin pressure outflow valve, V48.

(4) Replace the cabin pressure control module, P5-6. These are the tasks:

- Cabin Pressure Control Module Removal, AMM TASK 21-31-02-000-801,
- Cabin Pressure Control Module Installation, AMM TASK 21-31-02-400-801.

(a) Do the AMM test of the cabin pressure outflow valve that you did at the start of this task.

(b) If the system operates as specified in the AMM task, then you corrected the fault.

(c) If the system does not operate as specified in the AMM task, then continue.

(5) Replace the cabin pressure outflow valve, V48. These are the tasks:

- Aft Outflow Valve Assembly Removal, AMM TASK 21-31-03-000-801,
- Aft Outflow Valve Assembly Installation, AMM TASK 21-31-03-400-801.

(a) Do the AMM test of the cabin pressure outflow valve that you did at the start of this task.

(b) If the system operates as specified in the AMM task, then you corrected the fault.

--------- END OF CONTENT ---------

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details