PTF ALL

Maintenance Message 21-30010 - Fault Isolation

WIRING FROM CPC-1 TO CABIN PRESSURE SELECTOR PANEL HAS A FAULT
DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-1

CORRECTIVE ACTION SUMMARY

Repair Wiring D10724-D10738B
Repair Wiring D10724-D10738A
Repair Wiring Circuit Breaker C1270-D10738C
Repair Wiring Circuit Breaker C1270-D10726

A. Description

(1) This task is for this maintenance message:
  (a) WIRING FROM CPC-1 TO CABIN PRESSURE SELECTOR PANEL HAS A FAULT

(2) This fault can occur because of the failure of the wiring from CPC-1 to the cabin pressure selector panel.

B. Initial Evaluation

(1) Do this task:
  • Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Do this check of the wiring:
  (a) Disconnect connector D10724 from the cabin pressure control module, P5-6.
  (b) Remove the cabin pressure controller 1, M1653. This is the task:
    • Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801.
  (c) Do a wiring check between these pins of connector D10724 at the cabin pressure control module and these pins of connector D10738B at the E2-2 rack (WDM 21-31-11, WDM 21-31-22):

D10724		D10738B
pin 20	.....	pin A7
pin 21	.....	pin A8
pin 1	.....	pin B3
pin 4	.....	pin B7

  (d) Do a wiring check to make sure that pin 11 of D10724 has continuity to ground.
  (e) Do a wiring check to make sure that pin 12 of D10724 has continuity to ground.
  (f) If you find a problem with the wiring, then do these steps:
    1) Repair the wiring.
    2) Re-connect connector D10724 to the cabin pressure control module, P5-6.
    3) Re-install the cabin pressure controller 1, M1653. This is the task:
      • Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
    4) Do the AMM test that you did at the start of this task.
    5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.
  (g) If you do not find a problem with the wiring, then continue.

(2) Do this check of the wiring:

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

(a) Do a wiring check between these pins of connector D10724 at the cabin pressure control module and these pins of connector D10738A at the E2-2 rack (WDM 21-31-22):

D10724		D10738A
pin 9	.....	pin A1
pin 22	.....	pin A2
pin 26	.....	pin D15

(b) If you find a problem with the wiring, then do these steps:
1) Repair the wiring.
2) Re-connect connector D10724 to the cabin pressure control module, P5-6.
3) Re-install the cabin pressure controller 1, M1653. This is the task:
• Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
4) Do the AMM test that you did at the start of this task.
5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(c) If you do not find a problem with the wiring, then continue.

(d) Re-connect connector D10724 to the cabin pressure control module, P5-6.

(3) Do this check of the wiring:

(a) Open the PRESSURIZATION CONTROL AUTO 1 circuit breaker, C1270 [P6-4, F3].

(b) Do a wiring check between this terminal of circuit breaker C1270 and this pin of connector D10738C at the E2-2 rack (WDM 21-31-22):

C1270		D10738C
term =L	.....	pin 3

(c) Do a wiring check to make sure that pin 2 of D10738C has continuity to ground.

(d) If you find a problem with the wiring, then do these steps:
1) Repair the wiring.
2) Close the PRESSURIZATION CONTROL AUTO 1 circuit breaker, C1270 [P6-4, F3].
3) Re-install the cabin pressure controller 1, M1653. This is the task:
• Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
4) Do the AMM test that you did at the start of this task.
5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(e) If you do not find a problem with the wiring, then continue.

(f) Re-install the cabin pressure controller 1, M1653. This is the task:
• Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

(4) Do this check of the wiring:

(a) Disconnect connector D10726 from the cabin pressure control module, P5-6.

(b) Do a wiring check between this terminal of circuit breaker C1270 and this pin of connector D10726 at the cabin pressure control module (WDM 21-31-22):

C1270		D10726
term =L	.....	pin 20

(c) Do a wiring check to make sure that pin 21 of D10726 has continuity to ground.

(d) If you find a problem with the wiring, then do these steps:
1) Repair the wiring.
2) Close the PRESSURIZATION CONTROL AUTO 1 circuit breaker, C1270 [P6-4, F3].
3) Re-connect connector D10726 to the cabin pressure control module, P5-6.
4) Do the AMM test that you did at the start of this task.
5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details