PTF ALL

Maintenance Message 21-30021 - Fault Isolation

WIRING FROM CPC-2 TO OFV HAS A FAULT

DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-2

CORRECTIVE ACTION SUMMARY

Repair Wiring D10740B-D10734
Repair Wiring D10740A-D10734

A. Description

(1) This task is for this maintenance message:
   (a) WIRING FROM CPC-2 TO OFV HAS A FAULT

(2) This fault can occur because of the failure of the wiring from CPC-2 to the cabin pressure outflow valve.

B. Initial Evaluation

(1) Do this task:
- Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Do this check of the wiring:
   (a) Remove the cabin pressure controller 2, M1654. This is the task:
   - Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801.

   (b) Disconnect connector D10734 from the cabin pressure outflow valve, V48.

   (c) Do a wiring check between this pin of connector D10740B at the E1-1 rack and this pin of connector D10734 at the cabin pressure outflow valve (WDM 21-31-23):

D10740B		D10734
pin B5	.....	pin C-

   (d) If you find a problem with the wiring, then do these steps:
      1) Repair the wiring.
      2) Re-install the cabin pressure controller 2, M1654. This is the task:
      - Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
      3) Re-connect connector D10734 to the cabin pressure outflow valve, V48.
      4) Do the AMM test that you did at the start of this task.
      5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

   (e) If you do not find a problem with the wiring, then continue.

(2) Do this check of the wiring:
   (a) Do a wiring check between these pins of connector D10740A at the E1-1 rack and these pins of connector D10734 at the cabin pressure outflow valve (WDM 21-31-23):

D10740A		D10734
pin A7	.....	pin R
pin A8	.....	pin P
pin A9	.....	pin N
pin A10	.....	pin M

   (b) If you find a problem with the wiring, then do these steps:
      1) Repair the wiring.

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

2) Re-install the cabin pressure controller 2, M1654. This is the task:
   - Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
3) Re-connect connector D10734 to the cabin pressure outflow valve, V48.
4) Do the AMM test that you did at the start of this task.
5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details