PTF ALL

Maintenance Message 21-30030 - Fault Isolation

CABIN ALTITUDE IS HIGH AND OFV NOT FULLY CLOSED
DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-1

CORRECTIVE ACTION SUMMARY

Correct Related Maintenance Messages
Replace Cabin Pressure Outflow Valve [V48]
Replace Cabin Pressure Controller 1 [M1653]

A. Description

(1) This task is for this maintenance message:
  (a) CABIN ALTITUDE IS HIGH AND OFV NOT FULLY CLOSED

(2) This fault can occur because cabin altitude is high and the cabin pressure outflow valve not fully closed.

B. Initial Evaluation

(1) Do this task:
- Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Look in OMF Existing Faults for these related maintenance messages: 21-30300, 21-30301.
  (a) If you find any of the related maintenance messages, then do these steps:
    1) Do the fault isolation task for each related maintenance message.
    2) Do the AMM test that you did at the start of this task.
    3) If the OMF shows NOT ACTIVE for maintenance message 21-30030 (or if the message does not show), then you corrected the fault.
  (b) If you do not find related maintenance messages, then continue.

(2) Look in OMF Existing Faults, 36 Pneumatics for related maintenance messages.
  (a) If you find any related maintenance messages, then do these steps:
    1) Do the fault isolation task for each related maintenance message.
    2) Do the AMM test that you did at the start of this task.
    3) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.
  (b) If you do not find related maintenance messages, then continue.

(3) Replace the cabin pressure outflow valve, V48. These are the tasks:
- Aft Outflow Valve Assembly Removal, AMM TASK 21-31-03-000-801,
- Aft Outflow Valve Assembly Installation, AMM TASK 21-31-03-400-801.

  (a) Do the AMM test that you did at the start of this task.
  (b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.
  (c) If the OMF shows ACTIVE for the maintenance message, then continue.

(4) Replace the cabin pressure controller 1, M1653. These are the tasks:
- Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801,
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

  (a) Do the AMM test that you did at the start of this task.

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details