PTF ALL

Maintenance Message 21-30040 - Fault Isolation

CABIN DIFFERENTIAL PRESSURE IS HIGH

DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-1

CORRECTIVE ACTION SUMMARY

Replace Cabin Pressure Outflow Valve [V48]
Replace Cabin Pressure Controller 1 [M1653]
Replace Cabin Altitude/Differential Pressure Indicator [N51]
Repair Leak at Cabin Altitude/Differential Pressure Indicator [N51]

A. Description

(1) This task is for this maintenance message:

(a) CABIN DIFFERENTIAL PRESSURE IS HIGH

B. Initial Evaluation

(1) Do this task:

- Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) This maintenance message can show when there is not a failure in the system.

(a) The message can show if the airplane flies higher than the cruise altitude (FLT ALT) set by the flight crew.

(b) Look in OMF Fault History to find the flight leg when the maintenance message occurred.

(c) Do this task:

- Digital Cabin Pressure Controller NVM Download Procedure, AMM TASK 21-31-00-970-801.

(d) Examine the data for the flight leg when the maintenance message occurred.

(e) If the data shows that the airplane altitude for the flight leg was more than the FLT ALT value, then no maintenance action is necessary.

(2) Replace the cabin pressure outflow valve, V48. These are the tasks:

- Aft Outflow Valve Assembly Removal, AMM TASK 21-31-03-000-801,
- Aft Outflow Valve Assembly Installation, AMM TASK 21-31-03-400-801.

(a) Do the AMM test that you did at the start of this task.

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(c) If the OMF shows ACTIVE for the maintenance message, then continue.

(3) Replace the cabin pressure controller 1, M1653. These are the tasks:

- Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801,
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

(a) Do the AMM test that you did at the start of this task.

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(c) If the OMF shows ACTIVE for the maintenance message, then continue.

(4) Replace the cabin altitude/differential pressure indicator, N51. These are the tasks:

- Cabin Altitude and Differential Pressure Indicator Removal, AMM TASK 21-33-02-000-801,

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

- Cabin Altitude and Differential Pressure Indicator Installation, AMM TASK 21-33-02-400-801.

(a) Do the AMM test that you did at the start of this task.

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(c) If the OMF shows ACTIVE for the maintenance message, then continue.

(5) For the cabin altitude/differential pressure indicator, N51, do this check for leaks:

- Alternate Static System Low-range Leak Test, AMM TASK 34-11-00-790-805.

(a) If you find a leak, then do these steps:

1) Repair the leak.

2) Do the AMM test that you did at the start of this task.

3) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details