PTF ALL

Maintenance Message 21-30130 - Fault Isolation

MASTER OR SLAVE CONTROLLER PROGRAM PIN IS INCORRECT

DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-1

CORRECTIVE ACTION SUMMARY

Repair Wiring D10738B-D10740A

A. Description

(1) This task is for this maintenance message:

(a) MASTER OR SLAVE CONTROLLER PROGRAM PIN IS INCORRECT

B. Initial Evaluation

(1) Do this task:

- Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Do this check of the wiring:

(a) Remove the cabin pressure controller 1, M1653. This is the task:

- Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801.

(b) Remove the cabin pressure controller 2, M1654. This is the task:

- Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801.

(c) Do a wiring check between these pins of connector D10738B at the E2-2 rack and these pins of connector D10740A at the E1-1 rack (WDM 21-31-24):

D10738B		D10740A
pin B6	.....	pin A15
pin B2	.....	pin D3

(d) If you find a problem with the wiring, then do these steps:

1) Repair the wiring.

2) Re-install the cabin pressure controller 1, M1653. This is the task:

- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

3) Re-install the cabin pressure controller 2, M1654. This is the task:

- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

4) Do the AMM test that you did at the start of this task.

5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details