PTF ALL

Maintenance Message 21-30220 - Fault Isolation

ADIRU-L ARINC 429 RCVR SIGNAL IS INVALID

DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-1

CORRECTIVE ACTION SUMMARY

Do the applicable AMM Task(s)
Repair Wiring D3687A-D10738B
Replace Left Air Data/Inertial Reference Unit [M1749]

A. Description

(1) This task is for this maintenance message:
  (a) ADIRU-L ARINC 429 RCVR SIGNAL IS INVALID

(2) This fault can occur because of the left air data/inertial reference unit ARINC 429 receiver signal is an invalid.

B. Initial Evaluation

(1) Do this task:
- Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) For the left air data/inertial reference unit, M1749, do this task:
- Air Data Inertial Reference System - Operational Test, AMM TASK 34-21-00-710-801.

  (a) Do the AMM test that you did at the start of this task.

  (b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

  (c) If the OMF shows ACTIVE for the maintenance message, then continue.

(2) Do this check of the wiring:
  (a) Remove the left air data/inertial reference unit, M1749. This is the task:
- Air Data Inertial Reference Unit Removal, AMM TASK 34-21-01-000-801.

  (b) Remove the cabin pressure controller 1, M1653. This is the task:
- Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801.

  (c) Do a wiring check between these pins of connector D3687A at the E5-2 rack and these pins of connector D10738B at the E2-2 rack (WDM 21-31-24, WDM 34-21-14):

D3687A		D10738B
pin A9	.....	pin A3
pin B9	.....	pin A4

  (d) If you find a problem with the wiring, then do these steps:
    1) Repair the wiring.
    2) Re-install the left air data/inertial reference unit, M1749. This is the task:
- Air Data Inertial Reference Unit Installation, AMM TASK 34-21-01-400-801.
    3) Re-install the cabin pressure controller 1, M1653. This is the task:
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.
    4) Do the AMM test that you did at the start of this task.
    5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

(e) If you do not find a problem with the wiring, then continue.

(f) Re-install the cabin pressure controller 1, M1653. This is the task:
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

(3) Install a new left air data/inertial reference unit, M1749. To install it, do this task:
- Air Data Inertial Reference Unit Installation, AMM TASK 34-21-01-400-801.

(a) Do the AMM test that you did at the start of this task.

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details