PTF ALL

Maintenance Message 21-30331 - Fault Isolation

CPC-2 HAS AN INTERNAL FAULT

DETECTED BY: CABIN PRESSURE CONTROLLER (CPC)-2

CORRECTIVE ACTION SUMMARY

Replace Cabin Pressure Controller 2 [M1654]

A. Description

(1) This task is for this maintenance message:

(a) CPC-2 HAS AN INTERNAL FAULT

(2) The cabin pressure controller-2 has an internal fault.

B. Initial Evaluation

(1) Do this task:

- Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Replace the cabin pressure controller 2, M1654. These are the tasks:

- Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801,
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

(a) Do the AMM test that you did at the start of this task.

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details