PTF ALL

Maintenance Message 21-39000 - Fault Isolation

MORE THAN ONE SYSTEM HAS NO INPUT FROM CPC-1 ON CPC-1 OUTPUT BUS

DETECTED BY: IASC-L (AIR COND),IASC-R (AIR COND),DIGITAL FLIGHT DATA ACQUISTION UNIT (DFDAU)

CORRECTIVE ACTION SUMMARY

Replace Cabin Pressure Controller 1 [M1653]
Repair Wiring D10738A-D15838B
Repair Wiring D10738A-D15840B
Repair Wiring D10738A-D2295A

A. Description

(1) This task is for this maintenance message:

(a) MORE THAN ONE SYSTEM HAS NO INPUT FROM CPC-1 ON CPC-1 OUTPUT BUS

B. Initial Evaluation

(1) Do this task:

- Cabin Pressure Controller (CPC) BITE Procedure, AMM TASK 21-31-00-740-801.

(2) If the OMF shows ACTIVE for the maintenance message, then do the Fault Isolation Procedure below.

(3) If the OMF shows NOT ACTIVE for the maintenance message, then there was an intermittent fault.

C. Fault Isolation Procedure

(1) Replace the cabin pressure controller 1, M1653. These are the tasks:

- Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801,
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

(a) Do the AMM test that you did at the start of this task.

(b) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(c) If the OMF shows ACTIVE for the maintenance message, then continue.

(2) Do this check of the wiring:

(a) Remove the cabin pressure controller 1, M1653. This is the task:

- Cabin Pressure Controller (CPC) Removal, AMM TASK 21-31-01-000-801.

(b) Remove the left integrated air system controller, M2939. This is the task:

- Integrated Air Systems Controller (IASC) Removal, AMM TASK 21-61-22-000-801.

(c) Do a wiring check between these pins of connector D10738A at the E2-2 rack and these pins of connector D15838B at the E3-3 rack (WDM 21-31-24, WDM 21-51-12, WDM 31-35-04):

D10738A		D15838B
pin A5	.....	pin H14
pin A6	.....	pin H15

(d) If you find a problem with the wiring, then do these steps:

1) Repair the wiring.

2) Re-install the cabin pressure controller 1, M1653. This is the task:

- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

3) Re-install the left integrated air system controller, M2939. This is the task:

- Integrated Air Systems Controller (IASC) Installation, AMM TASK 21-61-22-400-801.

4) Do the AMM test that you did at the start of this task.

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details

5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(e) If you do not find a problem with the wiring, then continue.

(f) Re-install the left integrated air system controller, M2939. This is the task:
- Integrated Air Systems Controller (IASC) Installation, AMM TASK 21-61-22-400-801.

(3) Do this check of the wiring:

(a) Remove the right integrated air system controller, M2957. This is the task:
- Integrated Air Systems Controller (IASC) Removal, AMM TASK 21-61-22-000-801.

(b) Do a wiring check between these pins of connector D10738A at the E2-2 rack and these pins of connector D15840B at the E3-3 rack (WDM 21-31-24, WDM 21-51-22, WDM 31-35-04):

D10738A		D15840B
pin A5	.....	pin H14
pin A6	.....	pin H15

(c) If you find a problem with the wiring, then do these steps:

1) Repair the wiring.

2) Re-install the cabin pressure controller 1, M1653. This is the task:
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

3) Re-install the right integrated air system controller, M2957. This is the task:
- Integrated Air Systems Controller (IASC) Installation, AMM TASK 21-61-22-400-801.

4) Do the AMM test that you did at the start of this task.

5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

(d) If you do not find a problem with the wiring, then continue.

(e) Re-install the right integrated air system controller, M2957. This is the task:
- Integrated Air Systems Controller (IASC) Installation, AMM TASK 21-61-22-400-801.

(4) Do this check of the wiring:

(a) Remove the digital flight data acquisition unit, M675. This is the task:
- Digital Flight Data Acquisition Unit (DFDAU) Removal, AMM TASK 31-31-22-000-801.

(b) Do a wiring check between these pins of connector D10738A at the E2-2 rack and these pins of connector D2295A at the E3-2 rack (WDM 21-31-24, WDM 31-35-04):

D10738A		D2295A
pin A5	.....	pin A4
pin A6	.....	pin B4

(c) If you find a problem with the wiring, then do these steps:

1) Repair the wiring.

2) Re-install the cabin pressure controller 1, M1653. This is the task:
- Cabin Pressure Controller (CPC) Installation, AMM TASK 21-31-01-400-801.

3) Re-install the digital flight data acquisition unit, M675. This is the task:
- Digital Flight Data Acquisition Unit (DFDAU) Installation, AMM TASK 31-31-22-400-801.

4) Do the AMM test that you did at the start of this task.

5) If the OMF shows NOT ACTIVE for the maintenance message (or if the message does not show), then you corrected the fault.

--------- END OF CONTENT ---------

EXPORT CONTROLLED:9E991
BOEING PROPRIETARY - Copyright © - Unpublished Work - See title page for details