

How to install and configure a report in MET/TRACK® Software

Application Note

This document provides step-bystep instructions for installing a report for use in MET/TRACK® software, and/or in MET/CAL® Runtime. It applies to MET/TRACK and MET/CAL software versions 7.x.

- 1) First, you must save your report in your report directory. This directory is the main **Metcal** directory by default. If you are on a client/server installation, it will be on your shared network drive. If you are on a standalone installation, it will be in **C:\metcal** or **D:\metcal**. If you aren't using the default location save it in your directory location instead.
- Next, you will need to log in to the MET/TRACK application using the **Administrator** user name and password. By default these are **MT** and **MT**. But if you have changed the default password, use that instead.
- 3) Once MET/TRACK is open, select the **Setup** menu.
- 4) From the Setup menu, select **Install Reports**.
- 5) Select the filename of the report you want to add by clicking your mouse into the check box and clicking the sign.

6) Your screen will look something like Figure 1.




Figure 1

- When you are done, close the Install Reports window by clicking on the **X** but don't close out of MET/TRACK yet.
- Select the Setup menu again, and this time, select the Configure Reports menu item.

- 9) Find the filename (far right) of the report you just added and that you want to configure. You may need to drag some of the columns closed to view the filename. Your screen will look something like Figure 2.
- 10) If this is a report that you will not run at the end of a Runtime calibration, it is called a General Report. If it is a General Report, then you can select the check boxes of the forms from which you want to run the report. If you only want to run this report from the reports menu in MET/TRACK, you are finished. Just click the Save Changes button and close the Configure Reports window by clicking on the X.
- 11) If this is a report that you will run at the end of a Runtime calibration, then this is called a Runtime report. You will need to check the **Run** and the **Cal** boxes before you **Save Changes**.
- 12) Once you are finished, close out of the Configure Reports window by clicking on the **X**. If this is a Runtime report, continue to the next step.

escription	Comments	Author	Segregate	Reports	Run	Inv	Cal	Loc	Maint	Cust	Prompts	filename
eport of Calibration Ver 7 ONL	Report o:	Bill :	MT	▽							Y	rt_report_of_ca
eport of Calibration Ver 7 w/	Report o:	Bill :	MT	▽							Y	rt_report_of_ca
AA-w CALLOST12-30-2004A.RPT			MT	▽		▽			┍		Y	CALLOST12-30-20
ertificate of Calibration or F			MT	▽							Y	rt_certificate_
race report			MT	▽								trace.rpt
IMITED-PERFORMANCE-TORQUE-1/2"			MT	V	▽		┍				Y	labell-2_lim-pr
ALOVERDnorman.RPT FOR PROP (M			MT	▽							Y	CALOVERDnorman.
AA-D-CALOVERD_YES.RPT	over due		MT	V							Y	CALOVERD_YES.RE
eport of Calibration Ver 7	Report o:	Bill :	MT	V							Y	rt_ots_report_o
AA-D-OVERDUE PM'S LISTED IN CA			MT	▽							Y	CALOVERD_YESPM.
REVENTIVE MAINTENANCE CARDS OF			MT	V							Y	REP-CALDUECD_p.
TEMS DUE FOR CALIBRATION BY TE		Dan He	MT	V							Y	ITEMS DUE FOR (
ALOVERD_YES12-22-2004.RPT			MT	▽		┍			┍		Y	CALOVERD_YES12
AA-w CALLOST12-30-2004.RPT			MT	▽		┍			┍		Y	CALLOST12-30-20
AA-REPDUECD_plt.RPT	PREVENTI		MT	V		▽					Y	REPDUECD_plt.RI
- CALDUECD_SMT.RPT FOR BRIAN	CARDS FOI		MT	V							Y	CALDUECD_SMT.RI
LW-CAL-CERT	Report o:	Bill :	MT	V	▽		▽				Y	rt_ots_CERT_OF
LW-FAILURE FORM	Report o:	Bill :	MT	V	▽		┍				Y	rt_ots_report_o
LLOC-3 ALLOCCALms2.RPT			MT	V		▽					Y	ALLOCCALms2.RP
LLOC-4 ALLOCRPR-ms2.RPT			MT	▽		┍					Y	ALLOCRPR-ms2.R
IMITED-PERFORMANCE-1/2"-LABEL			MT	V	▽		┍				Y	labell-2_lim-p
ALIBRATION-STD-3/4"-LABEL			MT	V	▽		┍				Y	cal-STD-3-4-1al
ew lbl.rpt			MT	V	▽		V				Y	new_lbl.rpt

Figure 2

- Log in to **Runtime** with your regular user **ID** and **Pass**word.
- 14) Select the **Configure** menu and **Post Run Reports**.
- 15) Find your report in the **Available Reports** window and move it to the **Post Run Reports** window. To do this, highlight your report on the left and click the **right arrow**. You will see something like Figures 3 and 4.

16) Select OK.

You have completed the installation and configuration process and can now run your installed and configured report from the desired application.




Figure 3




Figure 4

Fluke. Keeping your world up and running.®

Fluke Corporation

PO Box 9090, Everett, WA USA 98206

Fluke Europe B.V.

PO Box 1186, 5602 BD Eindhoven, The Netherlands

For more information call:

In the U.S.A. (800) 443-5853 or Fax (425) 446-5116 In Europe/M-East/Africa +31 (0) 40 2675 200 or Fax +31 (0) 40 2675 222 In Canada (800)-36-FLUKE or

Fax (905) 890-6866 From other countries +1 (425) 446-5500 or

Fax +1 (425) 446-5116 Web access: http://www.fluke.com

©2007 Fluke Corporation. All rights reserved. Specifications subject to change without notice. Printed in U.S.A. 6/2007 3055841 A-EN-N Rev A Pub_ID: 11266-eng rev 01