

Work Order (WO) - Inspect/Correct Vibration on AFW Pump P-101A

Field	Value	Field	Value
WO ID	WO-2026-04567	Date	2026-02-07
System	AFW	Equipment	P-101A
Priority	High	Linked CR	CR-2026-00123

1. Task Description

Investigate elevated vibration alarm (≥ 5.0 mils) on P-101A observed during surveillance. Perform coupling alignment inspection, bearing condition checks, and post-maintenance verification run.

2. As-Found Condition

Coupling guard installed. Visible witness marks noted near coupling hub. No oil leaks observed. Vibration monitor channel VB-101A last recorded peak 6.2 mils.

3. Work Steps / Instructions

Step	Instruction
1	Establish clearance and verify electrical isolation per site lockout/tagout requirements.
2	Remove coupling guard and inspect coupling elements for wear or damage.
3	Check alignment using laser alignment tool LT-200. Record offset and angular values.
4	Inspect bearing housing temperature sensor and verify wiring integrity.
5	Reinstall coupling guard. Remove clearance as authorized.
6	Conduct controlled run: start P-101A and capture vibration spectrum; record flow and pressure.

4. Verification / Results

Parameter	Result	Acceptance	Pass/Fail
Alignment offset	2.5 mils	≤ 3.0 mils	PASS
VB-101A peak	3.8 mils	< 5.0 mils	PASS
FT-1102 flow	468 gpm	≥ 450 gpm	PASS
PT-1102 pressure	1185 psig	1000-1400 psig	PASS

5. As-Left Condition / Closeout Notes

Coupling alignment corrected (offset reduced from 4.1 mils to 2.5 mils). Vibration during verification run remained below alarm setpoint. WO closed.

Parts / Tools Used

Category	Item
Tool	Laser alignment tool LT-200
Tool	Vibration analyzer VA-3
Part	Coupling elastomer insert (PN 12-3456)