

Condition Report (CR) - Elevated Vibration on AFW Pump P-101A

Field	Value	Field	Value
CR ID	CR-2026-00123	Date Initiated	2026-02-06
System	AFW	Equipment	P-101A
Location	Turbine Building Elev. 468'	Initiator	Operator (Example)

1. Condition Description

During routine surveillance, AFW Pump P-101A exhibited elevated vibration after start. Vibration channel VB-101A peaked at 6.2 mils (alarm setpoint 5.0 mils) with stable flow at 465 gpm and discharge pressure at 1175 psig. No bearing temperature alarms were observed.

2. Immediate Actions

Operator stopped P-101A within 2 minutes of alarm. Control Room notified. Train A declared inoperable pending evaluation. Condition entered into the corrective action program.

3. Operability / Safety Significance

AFW Train B remained available. No safety injection or reactor trip occurred. This CR is categorized as low safety significance for training/test purposes.

4. Apparent Cause (if known)

Unknown at initiation. Potential contributors include reduced suction pressure margin and coupling misalignment.

5. Evidence / Data

Source	Value	Units	Notes
VB-101A peak	6.2	mils	Alarm setpoint 5.0 mils
FT-1102	465	gpm	Stable during event
PT-1102	1175	psig	Within normal range
Suction pressure	92	psig	Near lower bound of typical range

6. Planned Corrective Actions

Action ID	Action	Owner	Due
CA-1	Generate WO to inspect coupling alignment and check bearing condition.	Maintenance	2026-02-10
CA-2	Review suction pressure trend and confirm valve lineup / restrictions.	Operations	2026-02-08
CA-3	Perform vibration spectrum capture for 1x/2x indicators during controlled run.	Engineering	2026-02-12

Reference: Related Work Order planned: WO-2026-04567. Related evaluation: ECA-2026-0007 (if initiated).