DISTV-01

## 34. Audio system cannot be operated with air conditioner switches on the Rear Controller. (It can be operated with Panel Touch switches.)

## **INSPECTION PROCEDURE**

1 | Servicecheck[mode.[Audio[and[rear]A/Ccontrol[switch)](See[page[DI-1600]

CHEK

Troubleshoot for each diagnosis.

OK∏

Replace audio and rear A/C control switch See page BO-181).

**NCON** 

2[]

Check[]\*AVC-LAN@communication@circuit\*\*([See page DI-1716)[]

## CHECK:

 $Check \continuity \continuit$ 

## OK:

Continuity

NG

Replace[or[repair[AVC-LAN[circuit[See[page IN-35]]]]]

OK

Replace audio and rear A/C control switch (See page BO-181).