DISBS-02

14. Audio system cannot be operated with air conditioner switches on the Rear Controller. (It can be operated with Panel / Touch switches.)



1 | Service[check[mode[[Audio[and[]tear[A/C[control[switch)[[See[]page[DI-1551].

ОК

Replace the audio and rear A/C control switch.

NCON

2□

Check[]'AVC-LAN@communication@circuit"[[SeepageDI-1716]]

CHECK:

Check continuity of the wire harness between the rear A/C amplifier and the audio and rear A/C control switch.

OK:

Continuity

NG

Replace or repair AVC-LAN circuit.

OK

Replace audio and rear A/C control switch.