

Field Service Call Report

Name of the owner	SOUTH EAST CENTRAL RAILWAY	Machine name and Harsco serial number	TRT- 6190050												
Location of the machine	RAIPUR CHHATTISGARH	Engine hours	3668/14440 HMR												
		Software version	NA												
Visit started on	12-12-2025	Visit ended on	17-12-2025												
Purpose	The handling car Axle-5 and Axle-6 were kept in idle condition due to skidding.														
	The handling car Axle-5 and Axle-6 were kept in idle condition due to skidding. 1. The handling car Axle-5 and Axle-6 engage and disengage mechanism was activated. 2. Axle-5 and Axle-6 were inspected, and it was observed that the engage/disengage air connection valve of Axle-6 was damaged. However, the air supply hose pipe was connected as required. After this, fine adjustments were carried out through the traction pump linkage assembly to synchronize forward and reverse movement. 3. During the block, minor skidding was observed on Axle-1 & 2, Axle-5 & 6, and Axle-10. 4. After the block, synchronization of these axles was initiated, and it was found that the beam car traction pump was unable to maintain the null position due to internal leakage. Therefore, Axle-10 has currently been kept in idle condition, as it was providing uneven flow during traction synchronization. 5. After that, the remaining powered axles—Axle-1 & 2, Axle-3 & 4, and Axle-5 & 6—were set through the pump linkage assembly. It was observed that Axle-6 had almost negligible skidding, which is within the safe limit. 6. Work block was attended, and all axles were observed to be working properly except Axle-9 (Non-functioning) and Axle-10, which are currently in an idle state. Traction pump pressure <table><tr><td>Beam Car:</td><td>Handling Car:</td></tr><tr><td>Forward relief pressure: 4200 Psi</td><td>Forward relief pressure: 4000 Psi</td></tr><tr><td>Reverse relief pressure: 4200 Psi</td><td>Reverse relief pressure: 4000 Psi</td></tr><tr><td>Power Car Rear:</td><td>Power car Front:</td></tr><tr><td>Forward relief pressure: 4000 Psi</td><td>Forward relief pressure: 4200 Psi</td></tr><tr><td>Reverse relief pressure: 4000 Psi</td><td>Reverse relief pressure: 4200 Psi</td></tr></table> Note: Required pump pressure should be 5220 Psi @ 2100 RPM			Beam Car:	Handling Car:	Forward relief pressure: 4200 Psi	Forward relief pressure: 4000 Psi	Reverse relief pressure: 4200 Psi	Reverse relief pressure: 4000 Psi	Power Car Rear:	Power car Front:	Forward relief pressure: 4000 Psi	Forward relief pressure: 4200 Psi	Reverse relief pressure: 4000 Psi	Reverse relief pressure: 4200 Psi
Beam Car:	Handling Car:														
Forward relief pressure: 4200 Psi	Forward relief pressure: 4000 Psi														
Reverse relief pressure: 4200 Psi	Reverse relief pressure: 4000 Psi														
Power Car Rear:	Power car Front:														
Forward relief pressure: 4000 Psi	Forward relief pressure: 4200 Psi														
Reverse relief pressure: 4000 Psi	Reverse relief pressure: 4200 Psi														

Recommendation

1. The beam car traction pump needs to be replaced, as the currently installed pump is unable to maintain the null position due to internal leakage.
2. The Axle-6 engage and disengage valve needs to be installed.
3. The pump linkage assembly has play; it is recommended to replace the pump linkage assembly for proper traction synchronization.
4. It is recommended to install forward and reverse synchronization systems to improve traction efficiency in both directions.

Recommended Part list as per requirement:

Note: The parts required, as recommended by the Harsco Service Engineer on 11-11-2025, along with the currently recommended parts (For both directions forward & Reverse), are listed below.

Sr. No.	Part number	Description	Qty.
1	D4346Y22	Traction Pump	4
2	4005763	Linkage Assembly	1
3	0-201030-0-15	Front axle gear box Assembly (Beam Car)	1
4	4004156	TRACTION SYNCHRONIZATION ASSY.	2
5	5007373	ANGLE BRACKET FOR TRACTION SYNCHRONIZATION ASSY.	4
6	F023407	SCREW FOR TRACTION SYNCHRONIZATION ASSY.	8
7	F021122	FITTINGS FOR TRACTION SYNCHRONIZATION ASSY	8
8	F017896	PLUG FOR TRACTION SYNCHRONIZATION ASSY.	4
9	F013993	PLUG FOR TRACTION SYNCHRONIZATION ASSY.	4
10	F021905	FITTINGS FOR TRACTION SYNCHRONIZATION ASSY	8
11	NA	-4 HOSE PIPE FOR TRACTION SYNCHRONIZATION ASSY.	8
12	NA	AXLE-6 Air Valve	1
13	0-3307013-0-05	FLOW METER	1

Client's feedback/ remarks

Workman ship is good but problem not yet rectified completely due to requirements of spares as advised by SE/Harsco. Now axles No-6 skidding are under observation.

At present condition machine can work safely.

Signature of machine / site in-charge:	<i>Ravi</i> Sr. Sec. Engineer/TM M/c No. ATRT-050 At BMY Div. R...	Signature of Service Engineer:	<i>Kausht Kumar</i> Assistant Service-Manager Harsco Rail.
Date:	12-12-2025 S.E.C. Rly.	Date:	17-12-2025