

INC-2020-03: Small flange fire at T-302 mixer during hot work

Incident / Near-Miss Report: INC-2020-03 Category: fire_small

Date: 2020-03-11 Area: Area 3 Equipment: T-302

Title: Small flange fire at T-302 mixer during hot work

NARRATIVE:

Grinding spark ignited residue at a leaking mixer flange near T-302. Extinguished with DCP in under a minute. Gas test had been done 3 h before work started, not immediately prior.

ROOT CAUSE: Stale gas test; leaking flange not identified in JSA.

PRECURSOR CONDITIONS: hot work near live naphtha equipment; gas test older than 1 h

CORRECTIVE ACTIONS: SOP-HW-001 rev 3: gas test immediately before hot work; revalidation rule.

Associated permit: PTW-2020-0104

Reported to: M. Pillai (Safety Officer)