

Rotork IQ3 Actuator Manual - Section 6: Torque Alarms

DOC CONTROL
UNIT-4 LIBRARY

SECTION 6 - TORQUE MONITORING AND ALARMS

- 6.2 Intermittent high-torque alarm during travel commonly indicates seat/disc debris, stem lubrication breakdown, or scale build-up on isolation valves in cooling water duty.
- 6.3 Retrieve the torque-position log via the setting tool to identify the position band of the excursion before intrusive work.