

WORK ORDER WO-2023-0771

Work Order No: WO-2023-0771 Type: CM Priority: P3
Equipment: P-101 Date completed: 2023-07-22
Title: P-101 seal replacement (repeat failure)

FINDINGS / WORK PERFORMED:

Third monsoon seal failure since 2019 on this pump. R.K. Sharma closeout note: 'Suspect strainer bypass during monsoon - third time I've seen this since 2019. CW turbidity spikes after heavy rain at CT-101 basin, STR-101 blinds, pump cavitates briefly on start, seal faces open and ingest grit. Fix the water, not the seal. Recommend monsoon-mode weekly seal flush verification and STR-101 cleaning at dP 0.4 bar.'

Parts used: MS-40D cartridge seal x1, seal flush tubing

Labor hours: 16 Equipment downtime: 11 h

Raised by: A. Deshpande (Maintenance Planner)

Closed by: R. K. Sharma (Senior Reliability Engineer (retiring Dec 2026))

Reference drawing: D-CW-104 rev 3