

WORK ORDER WO-2025-0655

Work Order No: WO-2025-0655 Type: CM Priority: P3

Equipment: P-101 Date completed: 2025-06-28

Title: P-101 seal replacement at monsoon onset

FINDINGS / WORK PERFORMED:

Failure caught early by the new weekly monsoon seal-flush verification (SOP-CW-012 rev 3).

Downtime halved vs prior events. Root cause chain unchanged: CT-101 basin turbidity -> STR-101 blinding -> cavitation. Fleet check recommended: P-103 and P-107 share the same MS-40D seal model.

Parts used: MS-40D cartridge seal x1

Labor hours: 10 Equipment downtime: 4 h

Raised by: A. Deshpande (Maintenance Planner)

Closed by: R. K. Sharma (Senior Reliability Engineer (retiring Dec 2026))

Reference drawing: D-CW-104 rev 3