

WORK ORDER WO-2025-4471

Work Order No: WO-2025-4471 Type: breakdown Priority: P1

Equipment: P-101 Date completed: 2025-07-09

Title: P-101 tripped on high discharge temperature TI-1103

FINDINGS / WORK PERFORMED:

TI-1103 reached 68 degC (trip 65). Investigation: E-201 CW-side fouled - outlet approach temperature 9 degC above clean baseline; STR-101 dP 0.55 bar. E-201 backflushed, STR-101 cleaned, trip reset. Root cause: fouled cooler restricting CW flow (FI-1102 low). Monsoon turbidity again.

Parts used: none

Labor hours: 6 Equipment downtime: 3 h

Raised by: S. Venkatesan (Shift Supervisor)

Closed by: R. K. Sharma (Senior Reliability Engineer (retiring Dec 2026))

Reference drawing: D-CW-104 rev 3