GREY BANNER ALERT

mainroads WESTERN AUSTRALIA

SHW Serious Incident (SI) – Final Notice

Date of Incident	04/03/2026	**Time of Incident**	12:45 PM
Directorate / Region	GSR	**Main Roads or Contractor**	Main Roads
EQSafe Event Type	Injury/ Illness	**EQSafe Incident Number**	57148
Actual Consequence	Moderate	**Potential Consequence**	Moderate

Incident Short Description	Shoulder injury resulting in LTI

Executive Summary

IP attempted to pull-start pressure water pump in a gravel pit.

After attempting several pull-starts with no success, IP heard a popping sound and felt pain in their right shoulder and right side of their neck.

Work colleague & line manager were informed.

IP was transported to Albany hospital for medical assessment.
A certificate of no capacity was issued to IP 04/03/2026 to 11/03/2026.

ICAM Lite completed and contributing factors below identified.

Contributing Factors

- Pressure water pump was transported from one pit to another with the fuel line not isolated causing hydraulic lock in the line.
- Pressure was not released from the pressure wand trigger before attempting pull starts, also contributing to hydraulic lock.
- The pull cord on the pressure water pump was short preventing a full arm pull cord extension for the operator.

Incident Photos

Pressure Washer Pump full extension of pull cord prior to incident.

Corrective Actions

- Replacement of pressure washer pump pull cord with one of suitable length.
- Reaffirmed with pressure washer pump operator's requirement to release pressure with wand trigger before pull cord starts.
- Reaffirmed with operators to isolate pressure washer pump fuel line before transporting.

New longer pull cord installed on pressure washer pump

Distribution of Notice	Main Roads Personnel and Contracting Organisations