



GREY BANNER ALERT



SHW Serious Incident (SI) – Final Notice

Date of Incident:	23/07/2022	Time of Incident:	06:10am
Region / Directorate:	CNR / MWG	Main Roads or Contractor:	Contractor
EQSafe Event Type:	Damage / Loss	EQSafe Incident Number:	27714
Actual Consequence:	Minor	Potential Consequence:	Major

Incident Short Description:	Prime Mover collided with Water Cart
------------------------------------	--------------------------------------

Executive Summary:

On the 23rd of July 2022 at 06:13am, the Operator of a Hino 500 Water Cart exited the North Intersection from the Minilya Roadhouse whilst being incorrectly positioned. Upon entering North West Coastal Hwy, subsequent Operator inattention failed to also recognise any lights from an oncoming Freightliner Prime Mover and Double Trailer Combination. Consequently, this resulted in the Water Cart bull bar contacting the side of the Prime Mover fuel tank, the first trailer tyre and mirror-to-mirror contact.

Incident Photos:



Point of contact between Freightliner and Water Cart



Photos of inside of the Water Cart. Series of post event damage to the Water Cart, Freightliner and Trailer Rim / Tyre.

Contributing Factors:

- The Operator did not position the Water Cart to left of centre at the north intersection whilst performing a right-angle turn. The Operator cut the corner at the intersection and onto the other side of the road for the ease of turning slightly left into the Main Roads Depot access road.
- The Operator did not drive to State licensing and Road Traffic Code (2000) rules whilst performing a right-hand turn.
- The Operator perceived there was no oncoming traffic prior to the crest approach and turning onto NW Coastal Hwy.
- Operating on-highway trucks to turn from the north intersection into the Main Roads Depot access road is less than 20m.
- The rear cab window is blocked by the water tank; the extra-cab side windows are not featured on this model, combined with bright LEDs of the Water Cart blocking out other light sources this all contributed slightly to reducing visibility whilst travelling up a gradient of 4.6 degrees.
- The company did not evaluate the specific risk of on-highway trucks and other vehicles entering/exiting Minilya Roadhouse crossing the NW Coastal Hwy into the Main Roads Depot and or access road.
- As the event was primarily controlled by company WHS process, notification time to local Police office elapsed.

Corrective Actions:

- Main Roads and/or Minilya Roadhouse to evaluate improving the design criteria for entry and exit from Minilya Roadhouse.
- Review on-highway service truck build specification and vehicle risk assessment for the requirements of extra cab windows to be glass for additional visibility.
- Review the Traffic Management Plans for relevant company instruction and notification process to local Police in the event of traffic accidents.
- Risk assess and implement change management to the parking assembly requirements for the project; Intent is to limit travel movements from the project and interaction with the public and road users.

**Critical Risk:**

This serious potential incident aligns with the
Main Roads Critical Risk Profile relating to

Vehicles and Driving**Distribution of
Notice:**

Main Roads Personnel and Contracting Organisations