North Point Collision and Auto Center 159 Pennsylvania Ave W St Paul, MN 55103

Phone: (651) 292-1485 Email:autocare@1stopautocare.com

*** PRELIMINARY ESTIMATE ***

02/10/2023 07:40 AM

Cell: (651)855-8752

FAX:

Owner

Owner: Michael Goetz

Address: 1664 Cedar Ln

City State Zip: Newport, MN 55055

Email: m.goetz@comcast.net

Control Information

Claim #: 600-0606383-0 **Insured Policy #:** P005718047

Loss Date/Time: 01/31/2023 Loss Type: Collision

Deductible: \$500.00

Ins. Company: Country Financial

Insured: Michael Goetz

Address: 1664 Cedar Ln Cell: (651)855-8752

City State Zip: Newport, MN 55055 FAX:

Email: m.goetz@comcast.net

Claim Rep: Diane Boedeker

Work/Day: (855)864-9087 Address:

Inspection

Inspection Date: 02/10/2023 07:42 AM Inspection Type: Drive In

Inspection Location: North Point Collision & Auto Center Contact:

Address: 159 Pennsylvania Ave W. Work/Day: (651)292-1485x

City State Zip: Saint Paul, MN 55103 FAX:

Primary Impact: Front Secondary Impact:

Company: North Point Collision **Appraiser License #**: 20070001293

Contact: Jaswant A Teekasingh Address: 159 Pennsylvania Ave W Work/Day: (651)292-1485

Home/Evening: (651)292-1546 **FAX**: (651)292-1417 City State Zip: St Paul, MN 55103

Email: autocare@1stopautocare.com

Repairer

Contact: Jaswant A Teekasingh

Repairer: North Point Collision & Auto Center

Work/Day: (651)292-1485 Address: 159 Pennsylvania Ave W

Home/Evening: (651)292-1546 City State Zip: St. Paul, MN 55103 **FAX**: (651)292-1417

Email: autocare@1stopautocare.com

License #: 20070001293 Regulation ID: MNR000053587

Target Complete Date/Time: Days To Repair: 15*

02/10/2023 08:54 AM Page 1 of 7 2013 Chevrolet Tahoe LTZ 4 DR Wagon
Claim #: 600-0606383-0 02/10/2023 07:40 AM

Remarks

Insured approves the use of aftermarket parts

\$ 500.00 deductible applies and should be paid to the shop by the insured.

\$ 12,346.09 payment issued and mailed to North Point Collision

Repair Facility: Supplements require pre-approval for payment consideration.

Please send all Supplement requests including supporting photos

and invoices to: Unit5@countryfinancial.com

Vehicle

OEM Part Price Quote ID: ****

2013 Chevrolet Tahoe LTZ 4 DR Wagon 8cyl Gasoline 5.3 FLEX 6-Speed Automatic

Lic.Plate: HNF-766

Lic Expire:

Prod Date:10/2012Mileage:118,905Veh Insp#:Mileage Type:ActualCondition:Code:U7412A

Ext. Color: SWITCHBLADE SILVER MET Int. Color: Light Titanium/Dark Titanium (t. Refinish: Two-Stage Int. Refinish: Two-Stage

Ext. Refinish: Two-Stage Int. Refinish: Two-Stage Ext. Paint Code: 17,GAN Int. Trim Code: 836

Options - AudaVIN Information Received

20 Inch Alloy Wheels 4-Wheel Drive

Alarm System

Auto Adjust Suspension
Auto Locking Hubs (4WD)
Rose Sound System

Bose Sound System Center Console Climate Cntrl Frnt Seats

Digital Signal Processor Dual Air Conditioning Dual Pwr Lumbar Supports

Flip-Up Liftgate Window Full Size Spare Tire

Full Size Spare Tire Head Airbags

Heated Steering Wheel Intermittent Wipers Leather Steering Wheel

MP3 Decoder Navigation System Power Adjustable Pedals

Power Liftgate
Power Windows

Rear Seat Audio Controls Rear View Camera

Rem Trunk-L/Gate Release Roof Rack Cross Bars

Side Airbags

Stability Cntrl Suspensn Theft Deterrent System

Tilt Steering Wheel Tow Hooks Trailer Hitch XM Satellite Radio 2nd Row Head Airbags

AM/FM CD Player

Amplifier

Auto Headlamp Control
Automatic Dimming Mirror

Bucket Seats Chrome Grille Cruise Control Driver Information Sys

Dual Airbags

Electronic Transfer Case

Floor Mats

Garage Door Opener Heated Frnt & Rear Seats Heavy Duty Battery Keyless Entry System Lighted Entry System **Metallic Paint**

OnStar System
Power Brakes
Power Moonroof
Privacy Glass

Remote Starter

Rear Spoiler Rear Window Defroster

Roof/Luggage Rack Side Mirror Lighting Strg Wheel Radio Control

Third Seat (trucks)
Tinted Glass

Traction Control System

Trip Computer

3rd Row Head Airbags

Lic State: MN

VIN: 1GNSKCE05DR206100

Air Dam

Anti-Lock Brakes
Auto Load Leveling
Bodyside Moldings
Camper/Towing Package

Chrome Side Steps
Daytime Running Lights
Driver Seat Memory
Dual Power Seats

Emergency S.O.S. System

Fog Lights

Halogen Headlights Heated Power Mirrors Illuminated Visor Mirror

Leather Seats

Limited SIp Differential Mirror(s) Memory Overhead Console Power Door Locks Power Steering Rear Heater Rear Step Bumper

Rear Window Wiper/Washer Reverse Sensing System **Second Row Bucket Seats**

Skid Plates Tachometer

Three Zone Climate Ctrl Tire Pressure Monitor

Trailer BrakeWood Interior Trim

02/10/2023 08:54 AM Page 2 of 7

AudaVIN options are listed in bold-italic fonts

Strines And Moultimes	Dama	ges									
1 RI 439	Line	Ор	Guide	МС	Description	MFR.Part No.	Price	ADJ% B%	Hours	R	
1 RI 439	Stripes	And	Moulding	<u>qs</u>							
Section Continue					Mldg,Front Door Side LT	R & I Assembly			0.3*	SM	
S R	2	RI	440		Mldg,Front Door Side RT	R & I Assembly			0.3*	SM	
Front Rumper	3	RI			LT Sunshade	R & I Assembly			0.3*	SM*	
Front Rumper					>> Labor includes adhesive cl	ean up on outer door pane					
Front Function First Sumper Cover Front Bumper Replace Economy \$340.00° INC° SM S6 EC 6 Cover, Front Bumper Replace Economy \$340.00° INC° SM SW First Fi	4	RI								SM*	
S					>> Labor includes adhesive cl						
Fort											
Refnish											
1.7 Surface 1.6 Two-stage 1.7 Surface 1.7 Surface 1.7 Surface 1.7 Two-stage							\$340.00*				
	7	L	6	#	Cover,Front Bumper				3.0*	RF	
# = 10, 13 8											
# # 10, 13 8 N											
March Marc						0.7 Two-stage					
Sec											
10 E 97											
Part Front End Part And Lamps Replace Economy \$47.00* INC* SM											
Pront End Panel And Lamps											
12 EU 28	11	EC	13		Brkt,Front Bumper Mtg	Replace Economy	\$47.00*		INC*	SM	
13 E 36 Emblem, Grille 22830014 GM Part \$160.01 11 1NC* SM 14 EC 41 Headlamp Assy, Halogen LT Replace Economy \$156.00* 1NC* SM 15 EC 42 Headlamp Assy, Halogen RT Replace Economy \$156.00* 1NC* SM 16 N 973 Headlamp Saim Additional Labor 0.5* SM 17 N 950 Fog Lamps Aim Additional Labor 0.3* SM 18 EC 61 Brkt, Headlamp Mtg LT Replace Economy \$28.00* 1NC* SM 19 EC 62 Brkt, Headlamp Mtg RT Replace Economy \$33.00* 1NC* SM 19 EC 62 Brkt, Headlamp Mtg RT Replace Economy \$33.00* 1NC* SM 19 EC 62 Brkt, Headlamp Mtg RT Replace Economy \$33.00* 425.00 6.0* SM 10 EC 73 Panel, Radiator Supt Replace Recycled \$353.00* 425.00 6.0* SM 10 EC 73 Panel, Radiator Supt Replace Recycled \$353.00* 425.00 6.0* SM 10 EC 8 Panel, Radiator Supt Replace Recycled \$353.00* 425.00 6.0* SM 10 EC 8 Panel, Radiator Supt Replace Recycled \$350.00* 425.00 6.0* SM 10 EC 8 Panel, Radiator Supt Replace Recycled \$350.00* 425.00 6.0* SM 10 EC 8 Panel, Radiator Supt Replace Recycled \$350.00* 425.00 6.0* SM 10 EC 8 Panel, Radiator Supt Panel, Radiator, AC condenser, hood 10 EC 8 Panel, Radiator Supt Panel, Ra				Lan							
14 EC					•			+25.00			
15 EC 42 Headlamp Assy, Halogen RT Replace Economy \$156.00* INC* SM 16 N 973 Headlamps Aim Additional Labor 0.5* SM 17 N 950 Fog Lamps Aim Additional Labor 0.3 SM 18 EC 61 Brkt, Headlamp Mtg LT Replace Economy \$28.00* INC* SM 19 EC 62 Brkt, Headlamp Mtg RT Replace Economy \$33.00* INC* SM INC* INC* SM INC* INC* IN					· · · · · · · · · · · · · · · · · · ·						
Headlamps Air											
17							\$156.00*				
18 EC 61 Brkt, Headlamp Mtg LT Replace Economy \$28.00* INC* SM Brkt, Headlamp Mtg RT Replace Economy \$33.00* INC* SM SM SM SM SM SM SM S											
Radiator Support Panel, Radiator Sup											
Radiator Support Support Replace Recycled \$353.00* +25.00 6.0* SM											
Panel,Radiator Supt	19	EC	62		Brkt,Headlamp Mtg RT	Replace Economy	\$33.00*		INC*	SM	
>> LABOR: Time includes R&R/R&I headlamps, radiator, A/C condenser, hood >> lock, fan shroud assembly, washer reservoir, lower shield, upper panel >> mount panel, hood latch. D&R hood lock cable and wiring as necessary. 21 N Add for trans cooler Additional Labor \$0.00* 0.3* SM* 22 E 117 Label, Radiator Support 19354745 GM Part \$40.18 0.3* SM 23 E Caution label AC refrig Replace OEM \$34.88* INC* SM* 24 E 10 Baffle, Radiator Support Label > Part # 22737381 SM 25.17 0.1* SM 25 E 11 Baffle, Radiator Panel LT 15208497 GM Part \$53.17 0.1* SM 26 EC 77 Baffle, Radiator Panel RT 15208496 GM Part \$53.17 0.1* SM 27 E 11 Baffle, Radiator Panel Replace Economy \$53.00* INC* SM 27 E 27 Baffle Outer Replace OEM \$44.93* 0.1* SM* 28 E 28 E 18 E 18 E 18 E </td <td></td>											
Solock, fan shroud assembly, washer reservoir, lower shield, upper panel	20	EU	73						6.0*	SM	
Secological And Secological								lood			
21 N						-					
22 E 117 Label,Radiator Support 19354745 GM Part \$40.18 0.3* SM 23 E Caution label AC refrig Replace OEM \$34.88* INC* SM* >> Labor incl with Radiator Support Label >> Part # 22737381 24 E 10 Baffle,Radiator Panel LT 15208497 GM Part \$53.17 0.1* SM 25 E 11 Baffle,Radiator Panel RT 15208496 GM Part \$53.17 0.1* SM 26 EC 77 Baffle,Radiator Panel RT Replace Economy \$53.00* INC* SM 27 E RT Baffle Outer Replace OEM \$44.93* 0.1* SM* >> Part # 10392942 28 E LT Baffle Outer Replace OEM \$44.93* 0.1* SM* >> Part # 10392941 29 E 78 Baffle,Radiator Panel 22737374 GM Part \$52.50 INC* SM 30 E 627 Airbag Sensor,Front LT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning <td c<="" td=""><td>04</td><td>N.I.</td><td></td><td></td><td></td><td></td><td></td><td>•</td><td>0.0*</td><td>CN4*</td></td>	<td>04</td> <td>N.I.</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>•</td> <td>0.0*</td> <td>CN4*</td>	04	N.I.						•	0.0*	CN4*
Caution label AC refrig Replace OEM \$34.88* INC* SM*			447								
>> Labor incl with Radiator Support Label >> Part # 22737381 24 E 10 Baffle,Radiator Panel LT 15208497 GM Part \$53.17 0.1* SM 25 E 11 Baffle,Radiator Panel RT 15208496 GM Part \$53.17 0.1* SM 26 EC 77 Baffle,Radiator Panel Replace Economy \$53.00* INC* SM 27 E RT Baffle Outer Replace OEM \$44.93* 0.1* SM* >> Part # 10392942 28 E LT Baffle Outer Replace OEM \$44.93* 0.1* SM* >> Part # 10392941 29 E 78 Baffle,Radiator Panel 22737374 GM Part \$52.50 INC* SM 30 E 627 Airbag Sensor,Front LT 13502744 GM Part \$270.32 0.3* ME 31 E 628 Airbag Sensor,Front RT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning Cooling And Air Conditioning Replace Economy \$191.00* INC* SM			117								
24 E 10 Baffle,Radiator Panel LT 15208497 GM Part \$53.17 0.1* SM 25 E 11 Baffle,Radiator Panel RT 15208496 GM Part \$53.17 0.1* SM 26 EC 77 Baffle,Radiator Panel Replace Economy \$53.00* INC* SM 27 E RT Baffle Outer Replace OEM \$44.93* 0.1* SM* 28 E LT Baffle Outer Replace OEM \$44.93* 0.1* SM* 29 E 78 Baffle,Radiator Panel 22737374 GM Part \$52.50 INC* SM 30 E 627 Airbag Sensor,Front LT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning 32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM	23	E				•	\$34.88		INC	2IVI	
24 E 10 Baffle,Radiator Panel LT 15208497 GM Part \$53.17 0.1* SM 25 E 11 Baffle,Radiator Panel RT 15208496 GM Part \$53.17 0.1* SM 26 EC 77 Baffle,Radiator Panel Replace Economy \$53.00* INC* SM 27 E RT Baffle Outer Replace OEM \$44.93* 0.1* SM* >> Part # 10392942 Part # 10392941 \$44.93* 0.1* SM* 29 E 78 Baffle,Radiator Panel 22737374 GM Part \$52.50 INC* SM 30 E 627 Airbag Sensor,Front LT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning 32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM						pport Labei					
25 E 11 Baffle,Radiator Panel RT 15208496 GM Part \$53.17 0.1* SM 26 EC 77 Baffle,Radiator Panel Replace Economy \$53.00* INC* SM 27 E RT Baffle Outer Replace OEM \$44.93* 0.1* SM* 28 E LT Baffle Outer Replace OEM \$44.93* 0.1* SM* 29 E 78 Baffle,Radiator Panel 22737374 GM Part \$52.50 INC* SM 30 E 627 Airbag Sensor,Front LT 13502744 GM Part \$270.32 0.3* ME 31 E 628 Airbag Sensor,Front RT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning 32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM	24	_	10			15209407 CM Bort	¢52.47		0.1*	CM	
26 EC 77 Baffle,Radiator Panel Replace Economy \$53.00* INC* SM 27 E RT Baffle Outer Replace OEM \$44.93* 0.1* SM* 28 E LT Baffle Outer Replace OEM \$44.93* 0.1* SM* 29 E 78 Baffle,Radiator Panel 22737374 GM Part \$52.50 INC* SM 30 E 627 Airbag Sensor,Front LT 13502744 GM Part \$270.32 0.3* ME 31 E 628 Airbag Sensor,Front RT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning 32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM											
27 E RT Baffle Outer											
28 E LT Baffle Outer Seplace OEM \$44.93* 0.1* SM* 29 E 78 Baffle,Radiator Panel 22737374 GM Part \$52.50 INC* SM 30 E 627 Airbag Sensor,Front LT 13502744 GM Part \$270.32 0.3* ME 31 E 628 Airbag Sensor,Front RT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning 32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM			7.7								
28 E LT Baffle Outer > Part # 10392941 Replace OEM \$44.93* 0.1* SM* 29 E 78 Baffle,Radiator Panel 22737374 GM Part \$52.50 INC* SM 30 E 627 Airbag Sensor,Front LT 13502744 GM Part \$270.32 0.3* ME 31 E 628 Airbag Sensor,Front RT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning 32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM	21	_				Replace OEM	Φ44.93		0.1	SIVI	
>> Part # 10392941 29 E 78 Baffle,Radiator Panel 22737374 GM Part \$52.50 INC* SM 30 E 627 Airbag Sensor,Front LT 13502744 GM Part \$270.32 0.3* ME 31 E 628 Airbag Sensor,Front RT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning 32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM	20	_				Danless OFM	¢44.02*		0.1*	CN4*	
29 E 78 Baffle,Radiator Panel 22737374 GM Part \$52.50 INC* SM 30 E 627 Airbag Sensor,Front LT 13502744 GM Part \$270.32 0.3* ME 31 E 628 Airbag Sensor,Front RT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning 32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM	28					Replace OEM	Ф44.93°		0.1"	2IVI	
30 E 627 Airbag Sensor,Front LT 13502744 GM Part \$270.32 0.3* ME 31 E 628 Airbag Sensor,Front RT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning 32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM	20	_	7Ω			22727274 CM Dart	¢ 52 50		INIC*	CM	
31 E 628 Airbag Sensor,Front RT 13502744 GM Part \$270.32 0.3* ME Cooling And Air Conditioning 32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM											
Cooling And Air Conditioning 32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM											
32 EC 755 46 Radiator Replace Economy \$191.00* INC* SM	31	_	020		Alluay Selisul, Fluill KT	13302144 GIVI Part	ψ <i>21</i> U.3 <i>2</i>		0.3	IVI⊏	
33 EC 764 Tank,Coolant Recovery Replace Economy \$48.40* 0.4* SM				46							
	33	EC	764		rank,Coolant Recovery	Replace Economy	\$48.40*		0.4*	SM	

02/10/2023 08:54 AM Page 3 of 7

2013 Chevrolet Tahoe LTZ 4 DR Wagon
Claim #: 600-0606383-0 02/10/2023 07:40 AM

Claim #: 6	00-06063	883-0	rago	•				02/10/2	023 07:40 AM
34	EC	792		Blade,Engine Fan LT	Replace Economy	\$119.10*		INC*	SM*
	EC	793		Blade,Engine Fan RT	Replace Economy	\$107.34*		INC*	SM*
	EC	758	46	Shroud,Radiator	Replace Economy	\$354.83*		INC*	SM
37	N	977		A/C Evacuate & Recharg	Additional Labor	ψου 1.00		1.4*	ME
38	N	600		A/C Evac Rechrg & Rovr	Additional Labor			0.4*	ME
39	EC	731	16	Condenser, A/C		\$140.00*		INC*	SM*
					Replace Economy		. 25 00		
40	EU	730	40	Cooler, Trans Aux Oil	Replace Recycled		+25.00	0.6*	SM*
41	EC	1701		Pipe,Trans Oil Cooler	Replace Economy	\$111.85*		INC*	SM*
42	E	1972		Pipe,Trans Oil Cooler	15779543 GM Part	\$30.51*		INC*	SM*
43	EC	834	46	Cooler,P/S Pump Oil	Replace Economy	\$169.00*		0.3*	SM*
		and Wind	<u>Ishi</u> e						
	EC	83		Panel,Hood	Replace Economy	\$531.00*		1.0*	SM
45	L	83	10	Panel,Hood	Refinish			2.8*	RF
					1.8 Surface				
					1.0 Two-stage				
				>> 3.0 Refn					
				>> -0.2 Overlap Major Non-Adj.	Panel				
46	L	89		Hood Underside	Refinish			1.8*	RF
					1.8 Surface				
				>> 1.5 Refn					
				>> 0.3 Add for Clear Coat					
47	Е	96		Latch, Hood Panel	20763454 GM Part	\$202.78		INC*	SM
48	EC	84		Hinge, Hood Panel LT		\$113.00*		INC*	SM
			10		Replace Economy	φ113.00			
49	L	84	10	Hinge,Hood Panel LT	Refinish			0.3*	RF
					0.2 Surface				
		0.5			0.1 Two-stage	# 440.00#		0.04	
	EC	85		Hinge, Hood Panel RT	Replace Economy	\$113.00*		0.3*	SM
51	L	85	10	Hinge,Hood Panel RT	Refinish			0.3*	RF
					0.2 Surface				
					0.1 Two-stage				
52	EC	1397		Bracket,Hood Hinge LT	Replace Economy	\$69.00*		INC*	SM
53	EC	1398		Bracket,Hood Hinge RT	Replace Economy	\$69.00*		INC*	SM
54	Ε	86		Pad,Insulator Hood	15828995 GM Part	\$211.38		INC*	SM
55	E	513		Retainer, Hood Insulato	20064875 GM Part	\$50.22*		INC*	SM
				>> 9 @ \$5.58		•			
56	EC	103		Fender,Front LT	Replace Economy	\$557.00*		2.6*	SM
				>> LABOR: Time includes head			an		0
				>> battery tray and fender liner.			4P		
				>> and D&R ECM. Time is after					
57		102	10			eu.		2 /*	DE
31	L	103	10	Fender,Front LT	Refinish			3.4*	RF
					2.7 Surface				
				0.0 D. (0.7 Two-stage				
				>> 2.0 Refn					
				>> -0.4 Overlap Major Adj. Pan	el				
				>> 0.5 Add for Edge					
				>> 0.1 Add for Clear Coat					
				>> 1.0 Add for Inside & 0.2 Add	for Clear Coat				
58	Ν			LT Drill Mount Holes	Additional Labor	\$0.00*		0.4*	SM*
59	I	104		Fender,Front RT	Repair			5.0*	SM
60	L	104	10	Fender, Front RT	Refinish			2.2*	RF
				,	1.7 Surface				
					0.5 Two-stage				
				>> 2.0 Refn	o.o Two stage				
				>> -0.4 Overlap Major Adj. Pan	al				
					GI				
				>> 0.5 Add for Edging					
•	<u> </u>	407		>> 0.1 Add for Clear Coat	D 0 I A			2.2	C1.
61	RI	127		Guard,Fender Mud RT	R & I Assembly			0.2	SM
62	RI	171		Grille,Upper Cowl	R & I Assembly			0.5*	SM
63	RI	275		Panel,Upper Cowl Vent LT	R & I Assembly			INC*	SM
64	RI	276		Panel,Upper Cowl Vent RT	R & I Assembly			INC*	SM

Front Body Interior Sheetmetal

02/10/2023 08:54 AM Page 4 of 7

02/10/2023 07:40 AM

Claim # : 6	00-0606	383-0	•			02/10/2	023 07:40 AN
65	EC	71	Reinf,Front Fender LT	Replace Economy	\$52.00*	INC*	SM
	RI	102	Skirt,Inner Fender RT	R & I Assembly	**==	0.3*	SM
67	Ε	90	Brace,Front Fender LT	15185449 GM Part	\$29.53	INC*	SM
68	Ē	128	Brace,Front Fender LT	25815065 GM Part	\$48.48	0.1*	SM
			,		•		
Engine	And	Components	6				
69	E	741	Duct,Air Intake	15901934 GM Part	\$304.02	0.3*	SM*
			•				
Dashbo	oard A	And Compon	<u>ients</u>				
70	Ν	523	Scan,Post-Repair	Additional Labor		0.5*	ME
Front D	<u>oors</u>						
71	I	270	PnI,Front Door Outer LT	Repair		2.0*	SM
			>> Front edge damage from fe	<u>.</u>			
72	L	270 10	PnI,Front Door Outer LT	Refinish		1.8*	RF
				1.6 Surface			
				0.2 Two-stage			
			>> 2.4 Refn	_			
			>> -0.4 Overlap Major Adj. Pa	nel			
			>> -0.2 Base Coat Reduction		dos o As Alexandel		
70		074	>> full panel basecoat is not re		amg to the phi	4.0*	CNA
73		271	Pnl,Front Door Outer RT	Repair		1.0*	SM
74		271	>> Front edge damage from fe	Refinish		1.8*	RF
74	_	271	Pnl,Front Door Outer RT	1.8 Surface		1.0	KF
				INC Two-stage			
			>> 2.4 Refn	INC TWO-stage			
			>> -0.4 Overlap Major Adj. Pa	nel			
			>> -0.2 Base Coat Reduction	1101			
			>> Full panel basecoat is not i	required due to location of	f dma to the pnl		
75	RI	235	W/Strip,Belt Outer LT	R & I Assembly	ang to the pin	0.3*	SM
76	RI	236	W/Strip,Belt Outer RT	R & I Assembly		0.3*	SM
77	RI	342	PnI,Inner Door Trim LT	R & I Assembly		0.4*	SM
78	RI	343	Pnl,Inner Door Trim RT	R & I Assembly		0.4*	SM
79	Ε	255	N/Plate,Front Door LT	15825693 GM Part	\$94.62	0.2	SM
80	Ε	256	N/Plate,Front Door RT	15825693 GM Part	\$94.62	0.2	SM
81	RI	176	Mirror,Outer R/C LT	R & I Assembly		0.4*	SM
82		177	Mirror,Outer R/C RT	R & I Assembly		0.4*	SM
83	RI	416	Channel,Front Glass Ru LT	R & I Assembly		0.2*	SM
			>> Set back for outer panel re				
84	RI	417	Channel,Front Glass Ru RT	R & I Assembly		0.2*	SM
			>> Set back for outer panel re				
85		229	Handle,Front Door Otr LT	R & I Assembly		0.4*	SM
86	RI	230	Handle,Front Door Otr RT	R & I Assembly		0.4*	SM
	_		_				
		Rocker Pan		D 0 I A		0.5*	ON 4
	RI	181	Board, Running LT	R & I Assembly		0.5*	SM
88		572	Board, Running LT	R & I Assembly		1.0*	SM
89	RI	182	Board,Running RT	R & I Assembly		1.0*	SM
<u>Manua</u>	l Entr	ioo					
	L	M01	Clear Coat	Refinish		2.5*	RF
91	N	M03	Flex Additive	Additional Labor	\$5.00*	2.5	SM*
92		M17	Cover Car Exterior	Additional Labor	\$5.00*	0.2*	SM*
32	1.4	IVI I I	>> Primer	, additional Labor	ψ5.00	0.2	CIVI
93	Ν	M18	Set-Up And Measure	Additional Labor		2.0*	SM*
	SB	M60	Hazardous Waste Removal	Sublet Repair	\$3.00*	2.0	SM*
	EC	50	Cavity Wax	Replace Economy	\$10.00*	0.5*	SM*
96			Cover Car Bag & Mask	Additional Labor	\$5.00*	0.2*	SM*
	• •		>> Refinish		T		
97	Ν		Clean & Retape LT Frt Door	Additional Labor	\$5.00*	0.3*	SM*
- '			>> Left front door bodyside me				-
98	Ν		Clean & Retape RT Frt Door	Additional Labor	\$5.00*	0.3*	SM*
			•				

02/10/2023 08:54 AM Page 5 of 7

Less: Deductible

Net Total

\$500.00-

\$12,346.09

2013 Chevrolet Tahoe LTZ 4 DR Wago Claim # : 600-0606383-0	on						02/10/2	023 07:40 AM
99 SB	>> Right front Pre-Scan	door bodyside	molding Sublet R	epair	\$139.00*		0.5*	ME*
	>> Front air b	>> Front air bag sensors damaged, air bags did not deploy						
100 SB	2 Wheel Thrus		Sublet R		\$49.95*			SM*
101 N	Clean & Reta	oe LT	Additiona	al Labor	\$5.00*		0.3*	SM*
	>> LT Door S							
102 N		Clean & Retape RT		al Labor	\$5.00*		0.3*	SM*
	>> RT Door S	unshade						
102 Items								
	MC	Message						
	10	INCLUDES A	UDATEX TI	ME TO CLEA	R ENTIRE PANE	L		
	13				. TWO-STAGE AL			
	46	PRINTABLE A	ALTERNATE	PARTS CO	MPARE			
Estimate Total & Entri	es							
OEM Parts					\$2,146.52			
Other Parts					\$4,219.52			
Paint & Materials		19.9 H	lours @ \$5	52.00	\$1,034.80			
Line Item Markup					\$144.50			
Parts & Material Total						\$7,545.34		
Tax on Parts & Material			@ 7.8	375%		\$594.20		
Labor	Rate	Replace R Hrs	Repair Hrs	Total Hrs				
Sheet Metal (SM)	\$72.00	21.0	15.9	36.9	\$2,656.80			
Mech/Elec (ME)	\$125.00	0.6	2.8	3.4	\$425.00			
Frame (FR)	\$90.00							
Refinish (RF)	\$72.00	19.9		19.9	\$1,432.80			
Labor Total				60.2 H	lours	\$4,514.60		
Sublet Repairs				00.21	\$191.95	ψ1,011100		
Gross Total					+	\$12,846.09		

Alternate Parts Y/41/00/00/41/41 Cumulative 41/00/00/41/41 Zip Code: 55103 Default OEM Part Prices DT 02/10/2023 07:42 AM EstimateID 1053305999852576768 QuoteID **** Rate Name Default

Audatex Estimating 10.20.58 ES 02/10/2023 08:54 AM REL 10.20.58 DT 02/01/2023 DB 02/08/2023 State Disclosure:MN © 2023 Audatex North America, Inc.

3.9 HRS WERE ADDED TO THIS ESTIMATE BASED ON AUDATEX'S TWO-STAGE REFINISH FORMULA. ESTIMATE CALCULATED USING THE 2.5 HOUR MAXIMUM ALLOWANCE FOR TWO-STAGE REFINISH OF NON-FLEX, EXTERIOR SURFACES.

02/10/2023 08:54 AM Page 6 of 7 2013 Chevrolet Tahoe LTZ 4 DR Wagon
Claim #: 600-0606383-0 02/10/2023 07:40 AM

Op Codes

UE = Replace OE Surplus ET = Partial Replace Labor EP = Replace PXN

EU = Replace Recycled TE = Partial Replace Price PM = Replace PXN Reman/Reblt
UM = Replace Reman/Rebuilt L = Refinish PC = Replace PXN Reconditioned

UC = Replace Reconditioned TT = Two-Tone SB = Sublet Repair N = Additional Labor BR = Blend Refinish I = Repair

IT = Partial Repair CG = Chipguard RI = R & I Assembly

P = Check AA = Appearance Allowance RP = Related Prior Damage



This report contains proprietary information of Audatex and may not be disclosed to any third party (other than the insured, claimant and others on a need to know basis in order to effectuate the claims process) without Audatex's prior written consent.

© 2023 Audatex North America, Inc.

AUDATEX is a trademark owned by Audatex North America, Inc. All rights reserved.

02/10/2023 08:54 AM Page 7 of 7