PLANT 2 · QUALITY PROCEDURE

Fill Weight Checks

QP-303
Rev F

Effective	Owner	Prepared by	Approved by
2024-01-15	**Quality**	**P. Nakamura**	**H. Costa**

PURPOSE

Keep every bottle at or above the label claim without giving product away.

SCOPE

All filled product on Lines 1, 2 and 3.

ROLES

ROLE	RESPONSIBILITY
Operator	Takes and weighs the samples.
Line Lead	Reacts to results outside the action limits.
QA Technician	Reviews the charts each shift and places product on hold.
Maintenance Technician	Adjusts the filler.

PPE

- Safety glasses
- Safety shoes

TOOLS

- Check scale (0.1 g)
- Tare bottles

MATERIALS

None.

PROCEDURE

Sampling

STEP	WHO	ACTION
1	Operator	Once every hour, take 5 bottles in a row from the filler discharge.
2	Operator	Weigh each bottle on the check scale. Subtract the tare. Write the five weights and their average on FRM-QA-03 Fill Weight Chart.
3	Operator	Verify the check scale with the 1 kg test weight at the start of every shift.

Reacting

STEP	WHO	ACTION
4	Operator	Any single bottle below the lower limit: stop the line and tell the Line Lead.
5	Line Lead	Place all product since the last good check on hold as described in QP-315. Call the QA Technician.
6	Operator	Average above target by more than 4 g for two checks in a row: tell the Line Lead. Operators must not change the fill setpoint.
7	Line Lead	Call the Maintenance Technician to adjust the filler. Only the Maintenance Technician changes the setpoint, and the change is written on the chart.
8	QA Technician	Review every chart before the end of the shift and initial it.

Note: Limits and targets for each product are in WI-210.

RELATED DOCUMENTS

- WI-210 Filler Setup and Nozzle Check
- QP-315 Nonconforming Product and Hold

RECORDS

- FRM-QA-03 Fill Weight Chart

REVISION HISTORY

REV	DATE	CHANGE
F	2024-01-15	Setpoint changes restricted to maintenance after overfill findings.
E	2022-03-07	Sample size raised from 3 to 5.