ITEM	DESCRIPTION	YES	NO	Findings During Testing	Test Results
1.	Smoke Detector		Χ	-With dust inside and outside	-No response on smoke tester
	#1			-Spray Smoke Detector Maximum 3 times	-Repeat spray again but no response in the device
				Waxiiiaiii 5 tiiiles	-Repeat clean
					-After 3x spray no response
					on smoke tester
Analysis: After spraying of smoke tester, removal of the device from base to Reset contact point and					
cleaning did not show any improvement on the device. Hence device is declared not functioning and there is communication failure between device and FACP panel.					
2.	Smoke Detector#2		Х	Same as Smoke detector#1	Same as Smoke detector#1
Analysis: Same as Smoke detector#1					
3.	Smoke Detector			Same as Smoke detector#1	Same as Smoke detector#1
	#3				
Analysis: Same as Smoke detector#1					
4.	Smoke Detector		Х	With dust outside	Same as Smoke detector#1
	#4			-Difficulty in removing smoke detector head.	
				-Spray Smoke Detector	
				Maximum 3 times	
Analysis: Same as Smoke detector#1					
4.	Smoke Detector		х	-Elevation too high. Scaffolding	No response on smoke
	#5 At pump Area			or manual lift not possible to inspect inside of SD	tester
_					Causa as Curalia data et au #4
5.	Smoke Detector #6		Х	Same as Smoke detector#4	Same as Smoke detector#4
	At pump Area				
6.	Smoke Detector		Х	Same as Smoke detector#4	Same as Smoke detector#4
	#7 At pump Area				
7.	Manual Push		Х	-Push the button 3x	- Repeat pushing the button
	Button			-No audible response	
Analysis: Manual push button should have an audible alarm response after pushing the button. Hence this					
device is declared not functioning					
6.	Missing Bell		х	- Bell is missing. Only wiring is visible	-No test to be performed
7.	FACP			 with accumulated dust and dirt 	Measured supply voltage. Value 205 volts
				-with insect and rat "droppings"	Measured output voltage.
				-No light indicator	Value: 0 volts
				-No response on sounder,	
				system reset, fire report and	
				battery test when toggle pressed	
				-evidence of rusty enclosure	
Analysis: FACP is not functioning					