

Universal Transmitter



Special Tool(s)

 ST3093-A	Fluke 77-IV Digital Multimeter FLU77-4 or equivalent
--	---

Inspection and Verification

1. Verify the customer concern.
2. Visually inspect for obvious signs of mechanical or electrical damage.

Visual Inspection Chart

Mechanical	Electrical
• Universal transmitter	• Wiring, terminals or connectors

3. If an obvious cause for an observed or reported concern is found, correct the cause (if possible) before proceeding to the next step.
4. If the cause is not visually evident, verify the symptom. GO to [Symptom Chart](#).

Symptom Chart

Symptom Chart		
Condition	Possible Causes	Action
• The universal transmitter is inoperative	• Interior lamps concern • Universal transmitter (part of the LH sun visor)	• GO to Pinpoint Test A.

Pinpoint Tests

Pinpoint Test A: The Universal Transmitter is Inoperative

Normal Operation

The universal transmitter and LH vanity mirror lamp share the same circuits. Both components are part of the LH sun visor.

This pinpoint test is intended to diagnose the following:

- Interior lamps concern
- Universal transmitter (part of the LH sun visor)

PINPOINT TEST A : THE UNIVERSAL TRANSMITTER IS INOPERATIVE

A1 CHECK FOR VOLTAGE TO THE UNIVERSAL TRANSMITTER	
• Check the illumination of the universal transmitter by pressing one of the buttons.	
Does the red indicator on the universal transmitter illuminate?	
Yes	GO to A2 .
No	GO to A3 .
A2 PROGRAM A HAND-HELD TRANSMITTER TO THE UNIVERSAL TRANSMITTER	
• Program the universal transmitter. Refer to the Owner's Literature.	
Does the universal transmitter program successfully?	
Yes	The universal transmitter is OK. VERIFY the receiver unit operates correctly.
No	INSTALL a new LH sun visor assembly. REFER to Headliner — Exploded View in Section 501-05. TEST the system for normal operation.
A3 CHECK THE OPERATION OF THE LH VANITY MIRROR LAMP	
• Verify the operation of the LH vanity mirror lamp. Refer to Section 417-02.	
Does the LH vanity mirror lamp operate correctly?	
Yes	INSTALL a new LH sun visor assembly. REFER to Headliner — Exploded View in Section 501-05. TEST the system for normal operation.
No	REFER to Section 417-02 to continue diagnosis.