

Diablo Canyon Power Plant P.O. Box 56 Avila Beach, CA 93424

800.545.6000

October 16, 2012

PG&E Letter DCL-12-096

U.S. Nuclear Regulatory Commission ATTN: Document Control Desk Washington, DC 20555-0001 10 CFR 50.73

Docket No. 50-323, OL-DPR-82
Diablo Canyon Unit 2
<u>Licensee Event Report 2-2012-001-00, Failure to Meet Emergency Diesel Generator Technical Specifications</u>

Dear Commissioners and Staff:

Pacific Gas and Electric Company (PG&E) is submitting the enclosed Licensee Event Report (LER) regarding the discovery of a broken emergency diesel generator fuel oil booster pump drive belt and subsequent failure to meet plant technical specifications. PG&E is submitting this LER in accordance with 10 CFR 50.73(a)(2)(i)(B) and 10 CFR 50.73(a)(2)(v)(D).

PG&E makes no new or revised regulatory commitments (as defined by NEI 99-04) in this report.

This event did not adversely affect the health and safety of the public.

Sincerely,

Barry S. Allen Site Vice President

wrl8/6980/50507816

Enclosure

cc/enc:

Elmo E. Collins, NRC Region IV

Laura H. Micewski, Acting NRC Senior Resident Inspector

Joseph M. Sebrosky, NRR Senior Project Manager

INPO

Bdy 5. All

Diablo Distribution

						-	_					Series Spanish					
NRC FORM 366 U.S. NUCLEAR REGULATORY COMMIS					SION												
						Estimated burden per response to comply with this mandatory collection request: 80 hours. Reported lessons learned are incorporated into the licensing process and fed back to industry. Send comments regarding burden estimate to the FOIA/Privacy Section (T-5 F53), U.S. Nuclear Regulatory Commission, Washington, DC 20555-0001, or by internet e-mail to infocollects.resource@nrc.gov, and to the Desk Officer, Office of Information and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information											
LICENSEE EVENT REPORT (LER) (See reverse for required number of digits/characters for each block)								and Regulatory Affairs, NEOB-10202, (3150-0104), Office of Management and Budget, Washington, DC 20503. If a means used to impose an information collection does not display a currently valid OMB control number, the NRC may									
								not conduct or sponsor, and a person is not required to respond to, the information collection.									
1. FACILITY NAME							2. DOCKET NUMBER 3. PAGE										
Diablo Canyon Power Plant, Unit 2							05000-323 1 OF 4										
4. TITLE																	
Failu	re to	Meet Er	nergen	cy Die	sel Gener	ator T	echni)	cal S _l	peci	fica	tions						
5. EVENT DATE			6. LER NUMBER 7. I				7. REPORT DATE			8. OTHER FACILITIES INVOLVE							
монтн	MONTH DAY YEAR		YEAR	SEQUEN NUMBI		монтн	DAY	YEAI		FACILITY NAME						CKET NUMBER	
08	18	2012	2012	- 001	1 - 00	10	16	201	2	ACILIT	TY NAME				DOCKET	NUMB	ER
9. OPE	9. OPERATING MODE 11. THIS REPORT IS SUBMITTED PURSUANT TO THE REQUIREMENTS OF 10 CFR §: (Check all that apply)																
ĺ	_		20.2201(b) 20.2203(a)(3)(i) 20.2203(d) 20.2203(a)(3)(ii) 20.2203(a)(1) 20.2203(a)(4)					50.73(a)(2)(i)(C) 50.73(a)(2)(vi 50.73(a)(2)(vi 50.73(a)(2)(ii)(A) 50.73(a)(2)(vi									
	1							50.73(a)(2)(ii)(B) 50.73(a)(2)(viii									
			20.2203(a)(2)(i) 50.36(c)(1)(i)(A)					50.73(a)(2)(iii) 50.73(a)(2)(ix)(A)									
10. POV	VER LI	EVEL		2203(a)(2 2203(a)(2			36(c)(1)(36(c)(2)	(II)(A)		F	50.73(a)(2)(50.73(a)(2)(F	50.73(a 73.71(a			
	100)	2 0.	2203(a)(2	2)(iv)	_	50.46(a)(3)(ii) 50.73(a)(2)(v)(B) 73.71(a)(5)										
				2203(a)(2		=	73(a)(2)(50.73(a)(2)(v)(C) ☐ OTHER Specify in Abstract below as in NPC Form 366A								
			L 20.	2203(a)(2		LICENS	73(a)(2)(FOR	TUIC				or in NR			
FACILITY	NAME				12.	LICENS	EE CON	IIACI	FUR	Inic		TELEP	PHONE	NUMBER (Include A	rea Cod	le)
Wilb	ert R	. Landre			ry Service									45-698	0		
13. CON				3. COMPLETE ONE LINE FOR EACH COMPONEN MANU- REPORTABLE					[FAI	FAILURE DESCRIBED		IN THIS REPO		MANU-		REPORTABLE	
CAU	CAUSE SYSTEM		СОМ	PONENT	FACTURER		EPIX		CAUS	AUSE SYSTEM COMPO		COMPONE	FACTURER			TO EPIX	
14. SUPPLEMENTAL REPORT EXPECTED								1	PECTED ISSION		MONTH	DAY	Y	/EAR			
YES (If yes, complete 15. EXPECTED SUBMISSION DATE) NO										ATE							
					tely 15 single-s												
	_			-			-		-		ions personn						
			•		•						r pump (FOE 1. On Augus	,					5
			-		_	_	•				elt. The cau	-		-	-		
			-								llance test on	•					
ED	G 2-3	was ther	efore in	operable	e longer tha	an allov	ved by	TS 3.8	8.1.E	3.4,	and is thus re	portable	unde	er			
10	CFR	50.73(a)(2	2)(i)(B).														
Du	rino t	he time he	etwéen A	Amongt (3 2012 at	1304 P	DT an	d Ano	niet C	21 2	2012, at 0330	PDT FF)G 2	-2 was <i>e</i>	declar	he	
	_			-				_			inoperable, l	-				Ju	
	operable EDG, since the broken belt rendered EDG 2-3 inoperable. Two EDGs are required to be operable to mitigate																
the	cons	equences	of a des	ign basi	s accident,	making	g this si	ituatio	n rej	porta	able under 10) CFR 50.	.73(a	ı)(2)(v)(D).		
PG	&E u	vill reduce	the ED	G 2-3 d	rive helt te	nsion s	necific	ation i	n nl:	ant r	procedures pe	ending ve	ndor	annrov	al Pr	3&F	
ř						-	_		-	_	present cond	-		~ ~			

strategy.

NRC FORM 366A

(10-2010)

LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	е	3. PAGE				
Diable Convey Devel Dland Haid 2	05000 222	YEAR	SEQUENTIAL NUMBER	REV NO.	2	OF	4
Diablo Canyon Power Plant, Unit 2	05000-323	2012	- 001 - 00		2	OF	4

NARRATIVE

I. Plant Conditions

On August 18, 2012, Unit 2 was in Mode 1 (Power Operation) at 100 percent power.

II. Problem Description

A. Background

Diablo Canyon Power Plant (DCPP) Unit 2 has three emergency diesel generators (EDGs) [DG] that provide vital backup power to three electrical buses [BU] to mitigate the consequences of a design basis accident (DBA) whenever normal or off-site power sources are unavailable. DCPP EDGs are designed to function so that a single failure of any EDG will not jeopardize the capability of the remaining EDGs to start and provide power to operate the shutdown systems required to mitigate any DBA condition.

Each EDG has a single fuel oil booster pump (FOBP) [P] driven by a belt connected to the EDG crankshaft extension shaft. The FOBP supplies fuel oil from the diesel engine's day tank [TK] to each cylinder's fuel oil injection pump. The engine fuel oil system [DC] and FOBP are required for diesel operation. However, because of the independence of each diesel and its associated powered bus, a single failure involving one diesel will not cause a failure of any other EDG to perform its designed safety functions.

B. Event Description

On August 18, 2012, the DCPP Unit 2 Operations turbine building (TB) watch discovered a broken EDG 2-3 FOBP belt. Operators declared EDG 2-3 inoperable, entering Technical Specification (TS) 3.8.1, "AC Sources - Operating," Condition B, "One DG inoperable." TS 3.8.1 and its associated TS Bases required EDG 2-3 to be returned to operable within 7 days for unplanned maintenance. Security personnel evaluated the as-found condition of the EDG 2-3 drive belt and concluded that the belt had not been broken due to sabotage. The other five EDGs have different FOBP belts, which cause lower side loading on the pumps. Plant engineers and operators walked down all five other EDGs and found no visible damage of the belts or FOBPs.

Plant personnel evaluated the pump's internal material condition. Normally, the FOBP easily rotates by hand with no drive belt attached. The FOBP would not rotate. Plant staff disassembled the pump and identified significant and uneven wear within the shaft bushing, significant and uneven scoring wear on the pump case faces, and galling on the internal gear [GR] faces, indicative of side loading on the pump. With normal side loading and adequate lubrication, the bushing would not be expected to wear unevenly and lead to shaft skewing. However, with excessive side loading, this would be expected to occur.

DCPP Engineering performed a thorough evaluation of plausible causes of the broken belt and seized FOBP that included discussions with the EDG vendor and FOBP vendor. Based upon the inspection results and vendor discussions, DCPP Engineering concluded that the FOBP drive belt failed because the FOBP seized. The FOBP seized because the excessive drive belt tension caused uneven side loading, bushing wear, and shaft skewing. This

NRC FORM 366A

10-2010)

LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION **CONTINUATION SHEET**

1. FACILITY NAME	2. DOCKET	6	3. PAGE				
Diable Common Direct Held 2	0,5000, 222	YEAR	SEQUENTIAL NUMBER	REV NO.	,	05	4
Diablo Canyon Power Plant, Unit 2	05000-323	2012	- 001 -	00	3	OF	4

NARRATIVE

prevented pump sheave rotation that resulted in the belt snapping during coast-down on August 3, 2012, at 1304 PDT, following EDG 2-3's satisfactory performance of DCPP Surveillance Test Procedure (STP) M-9A, "Diesel Engine Generator Routine Surveillance Test."

On August 20, 2012, DCPP Maintenance personnel replaced the FOBP and its drive belt. On August 21, 2012, at 0330 PDT, PG&E declared EDG 2-3 operable. PG&E failed to meet TS 3.8.1, Condition B, "One DG inoperable," because EDG 2-3 was not returned to operable status within the required 7-day completion time for unplanned maintenance after EDG 2-3 belt and FOBP failure following the test run on August 3, 2012, at 1304 PDT.

During the time between August 3, 2012, at 1304 PDT, and August 21, 2012, at 0330 PDT, EDG 2-2 was taken out of service and declared inoperable twice to perform surveillance testing. However, EDG 2-2 was still available for use via manual operator action. For those periods that EDG 2-2 was declared inoperable, DCPP Unit 2 only had one operable EDG, when two are required to be operable to perform the designed safety function of providing vital emergency power. This condition would have prevented the fulfillment of the EDG's designed safety function of mitigating the consequences of a DBA.

C. Status of Inoperable Structure, Systems, or Components That Contributed to the Event

None.

D. Other Systems or Secondary Functions Affected

None.

E. Method of Discovery

The DCPP Unit 2 Operations turbine building watch discovered the broken EDG 2-3 FOBP belt.

F. Operator Actions

DCPP Operators entered TS 3.8.1, "AC Sources - Operating," declaring EDG 2-3 inoperable.

G. Safety System Responses

None.

III. Cause of the Problem

The EDG 2-3 FOBP seized because the vendor-recommended drive belt tension caused excessive side loading and shaft skewing. The drive belt broke because the FOBP seized, preventing sheave rotation, resulting in the drive belt snapping during coast-down of EDG 2-3 following surveillance testing.

NRC FORM 366A (10-2010) LICENSEE EVENT REPORT (LER) U.S. NUCLEAR REGULATORY COMMISSION CONTINUATION SHEET

1. FACILITY NAME	2. DOCKET	6. LER NUMBER			3. PAGE		
Diable Convey Device Dland 11.14.2	05000 222	YEAR	SEQUENTIAL NUMBER	REV NO.	4	OF	4
Diablo Canyon Power Plant, Unit 2	05000-323	2012	012 - 001 - 00		4	OF	4

NARRATIVE

IV. Assessment of Safety Consequences

PG&E's quantitative risk analysis for the 18 days between the time EDG 2-3 was last successfully run on August 3, 2012, and the time when EDG 2-3 was declared operable on August 21, 2012, after replacing the FOBP and its drive belt, concluded that the incremental conditional core damage probability was less than the 1.0E-06 risk significance threshold. This event was a Safety System Functional Failure, but it is not considered risk significant and did not adversely affect the health and safety of the public.

- V. Corrective Actions
- A. Immediate Corrective Actions

On August 20, 2012, DCPP Maintenance personnel replaced the FOBP and its drive belt.

- B. Other Corrective Actions
- 1) DCPP will reduce the EDG 2-3 drive belt tension specification in procedure MP M-21.7B, "Diesel Engine 2-3 Fuel Oil Booster Pump," to a lower vendor-approved deflection force value.
- 2) DCPP will establish a periodic replacement strategy for the FOBP.
- VI. Additional Information
- A. Failed Components
- 1) The EDG 2-3 FOBP.
- 2) The EDG 2-3 FOBP drive belt.
- B. Previous Similar Events

None.