

STANDARD OPERATING PROCEDURE FOR FORMING

- Relevant PPE's such as hand gloves, safety helmets, and safety shoes are to be used.
- Identify the coil with sticker. Check coil width and thickness before loading. If it is within specification as per the Supervisor's instructions load the coil on pay off.
- Coil is then lifted with help of EOT crane.
- When coil is passed to mandrel, it has to be expanded and fix to the coil ID.
- Down the Snubber roll till it contacts to the coil.
- Binding strips are to be removed by binding cutter manually.
- Feed is given to the lead end of the sheet using pinch roll.
- Then the sheet is passes through loop pit table.
- Ensure that coil sheet enters through the entry guides/ pass before first pass.
- Coolant should be supplied as and when required from the coolant tank to the rollers.
- Observe profile dimensions, place intermediates guide wherever required.
- Check the profile dimensions and straightness before the profile enters cut-off tool and make necessary adjustment
- In case deviation persists inform superiors and make necessary corrections as per instructions.
- Adjust run off table as per the formed profile dimension.
- Adjust the length sensing device for the required length using encoder wheel.
- Cut the profile to the length adjusted and check all the dimensions of profile twist and bow with bow stand, for measuring camber use thread & for length use measuring tape
- If not Ok, make the necessary adjustments.
- If found Ok get clearance from shift In-charge and start production.
- While shearing the components check burr, bending if it is not ok then inform to shift incharge.
- Ensure use of gloves while removing the components from the run off table.
- Note down the profile dimensions in the mill report at regular intervals.
- For every 10 number of profiles, check the profile length.
- After forming sheet, the edges are grinded by hand grinding machine if required.
- Place the components in stacking order and bind using binding strip.
- If the component is of length more than 2 meters use lifting beam to lift with EOT crane to designated place.