

STANDARD OPERATING PROCEDURE FOR CRS-5 SLITTING

- Relevant personal protective equipment to be used by operator
- Identify the coil with sticker
- Transfer the coil by means of EOT crane to uncoiled pedestal/saddle
- Stock of rust preventive oil in storage tank to be checked and it should be filled as per level.
- For above work use pathway and ladder provided at machine.
- Ensure / check availability of fire extinguisher & water during the starting of soot cleaning process.
- Put the uncoiler mandrel in collapsed position and load the coil to uncoiled mandrel with the help of coil car.
- Expand the uncoiler mandrel after placing the coil at centre of the mandrel
- Snubber is rolled down and the binding strip is cut using binding cutter tool.
- Lower the pinch roll and run it in forward direction, operator should not stand front of the coil
- Cut the unrolled portion length and the sample is given to quality inspector for properties checking
- Make setting at slitter arbor and pass line or underarm setting at drag board if necessary at over arm on recoiler.
- Pass the sheet through entry guide roll unit to slitter arbor
- From slitter shearing scrap on both edges is wound on scrap winder, scrap removal with full hand sleeves
- Slit parts are taken to the coiler through drag board unit, pinch rolls, exit deflector roll and coiler roller.
- Insert the slit parts in to the coiler gripper and expand the mandrel
- Check the Initial winding at recoiler before putting machine run mode
- Adjust drag board and brake pressure
- Avoid overlap if it is multiple setting.
- Make ready the Rust Preventive oil in tank then start the line as clearance for quality check about properties
- Soot cleaning system is introduced to clean surface of the strip with kerosene wiping (if required), In each shift cleaning of floor / house keeping to be done
- Coil is cut and recoiled after slitting as per customer outer diameter
- Slit coil is stripped out to turn style
- Line is stopped in between for visual inspection, thickness checking and properties checking
- Write the production report

Don't DOs:

- During running or in idle condition operator should not cross through equipment to reach drive side.
- Don't use other than hammer during setting change for unlock / lock of nuts at upper arm / under arm and at slitting head.