Page 1: Vibration Limits

Vibration severity guide for rotating machines. Below 4.5 mm/s RMS the machine is in good condition. Between 4.5 and 7.1 mm/s raise a warning and plan an inspection. Above 7.1 mm/s treat it as an alarm: suspect bearing wear or imbalance and inspect the bearings the same shift.

Page 2: Temperature Monitoring and Thermography

Bearing housing temperature above 80 C is a warning, above 95 C is an alarm. Use an infrared camera monthly and compare against the baseline image. A temperature rise of more than 15 C in a week with rising vibration points to lubrication failure or bearing wear.

Page 3: Ultrasonic Thickness Monitoring

Measure wall thickness at fixed test points every 6 months. Calculate wall loss as a percentage of nominal thickness. Ten percent loss is a warning and twenty percent is an alarm that requires corrosion repair or section replacement.